



序号	报告编号	发布日期	结论	影像资料
46	:GX-B1416/22-Y-23097	2024年1月5日	综合判定：合格。	 A photograph showing a worker in a white protective suit and red helmet standing on a metal walkway in an industrial setting. The worker is looking towards the right. The background shows various pipes and machinery. A yellow timestamp '2023/12/22' is visible in the bottom right corner of the image.
47	:GX-B1416/22-Y-23098	2024年1月5日	综合判定：合格。	 A photograph showing two workers in orange protective suits and red helmets working in a dark industrial environment. One worker is holding a white document, and the other is looking at it. The background shows various pipes and machinery. A yellow timestamp '2023/12/24' is visible in the bottom right corner of the image.

48	:GX-B1416/22-Y-23099	2024年1月5日	综合判定：合格。	
49	GX-B1559/22-Y-23025	2024年1月8日	所检项目合格。	

50	GX-B1559/22-Y-23026	2024年1月8日	所检项目合格。	 <p>2023/12/21</p>
51	GX-B1559/22-Y-23027	2024年1月8日	所检项目合格。	 <p>2023/12/21</p>

52	GX-B1517/20-Y-23028	2024年1月8日	综合判定：合格。	
53	GX-B1521/20-Y-23642	2024年1月8日	所检项目合格。	

54	GX-B1521/20-Y-23643	2024年1月8日	所检项目合格。	
55	GX-B1310/21-Y-23200	2024年1月8日	符合标准要求。	

56	GX-B1499/23-Y-23118	2024年1月8日	所检项目合格。	
57	GX-B1499/23-Y-23119	2024年1月8日	所检项目合格。	

58	GX-B1499/23-Y-23120	2024年1月8日	所检项目合格。	 <p>2023/12/24</p>
59	GX-B1354/20-Y-24001	2024年1月8日	所检项目合格	 <p>2024/1/2</p>

60	GX-B1354/20-Y-24002	2024年1月8日	所检项目合格	 <p>A photograph showing a person in a white shirt and dark pants kneeling on the floor of a room filled with rows of white electrical control panels. The person is looking at a device in their hands. A yellow date stamp '2024/1/2' is visible in the bottom right corner of the image.</p>
61	GX-B1556/22-Y-23008	2024年1月8日	所检项目合格。	 <p>A photograph of a yellow tracked bulldozer on a dirt construction site. Two people, one in a white jacket and one in a red safety vest, are standing in front of the bulldozer. A blue sign on the bulldozer reads '新南一路 施工区-701'. A yellow date stamp '2023/12/7' is visible in the bottom right corner of the image.</p>

62	GX-B1415/22-Y-23022	2024年1月9日	综合判定：合格。	
63	GX-B1415/22-Y-23023	2024年1月9日	综合判定：合格。	

64	GX-B1539/22-Y-23297	2024年1月9日	所检项目合格。	
65	GX-B1539/22-Y-23298	2024年1月9日	所检项目合格。	

66	GX-B1557/22-Y-23053	2024年1月7日	所检项目合格。	
67	GX-B1521/20-Y-23644	2024年1月9日	所检项目合格。	

68	GX-B1521/20-Y-23645	2024年1月9日	所检项目合格。	 <p>A photograph showing the silhouette of a yellow excavator against a bright sunset sky. The sun is low on the horizon, creating a strong backlight effect. The excavator's arm and bucket are visible in the foreground. A yellow date stamp '2023/12/25' is located in the bottom right corner of the image.</p>
69	GX-B1521/20-Y-23646	2024年1月9日	所检项目合格。	 <p>A photograph of a yellow excavator with the number '51' on its arm, positioned on a dirt surface. The background shows a large, snow-covered embankment or hillside under a cloudy sky. A yellow date stamp '2023/12/25' is located in the bottom right corner of the image.</p>

70	GX-B1521/20-Y-23647	2024年1月9日	所检项目合格。	 A yellow tracked excavator with 'XC 50' written on its arm, positioned on a dirt construction site. A yellow date stamp '2023/12/25' is visible in the bottom right corner of the image.
71	GX-B1521/20-Y-23648	2024年1月9日	所检项目合格。	 A blue tracked excavator with '90 MAG' written on its arm, positioned on a dirt construction site. A yellow date stamp '2023/12/25' is visible in the bottom right corner of the image.

72	GX-B1521/20-Y-23649	2024年1月9日	所检项目合格。	
73	GX-B1521/20-Y-23650	2024年1月9日	所检项目合格。	

74	GX-B1521/20-Y-23651	2024年1月9日	所检项目合格。	
75	GX-B1521/20-Y-23652	2024年1月9日	所检项目合格。	

76	GX-B1521/20-Y-23653	2024年1月9日	所检项目合格。	
77	GX-B1521/20-Y-23654	2024年1月9日	所检项目合格。	

78	GX-B1521/20-Y-23655	2024年1月9日	所检项目合格。	
79	GX-B1521/20-Y-23656	2024年1月9日	所检项目合格。	

80	GX-B1521/20-Y-23657	2024年1月9日	所检项目合格。	
81	GX-B1521/20-Y-23658	2024年1月9日	所检项目合格。	

82	GX-B1556/22-Y-23009	2024年1月8日	所检项目合格。	
83	GX-B1556/22-Y-23010	2024年1月8日	所检项目合格。	

84	GX-B1556/22-Y-23011	2024年1月8日	所检项目合格。	
85	GX-B1563/21-Y-23047	2024年1月9日	所检项目合格。	

86	GX-B1557/22-Y-23051	2024年1月7日	所检项目合格。	
87	GX-B1557/22-Y-23052	2024年1月7日	所检项目合格。	