


序号	报告编号	发布日期	结论	影像资料
3	GX-B1559/22-P-23177	2024. 1. 7	所检项目合格。	
4	GX-B1559/22-P-23178	2024. 1. 7	所检项目合格。	

5	GX-B1559/22-P-23179	2024. 1. 7	所检项目合格。	
6	GX-B1559/22-P-23180	2024. 1. 7	所检项目合格。	
7	GX-B1417/22-P-231474	2024. 1. 7	综合判定：合格。	

8	GX-B1417/22-P-231475	2024. 1. 7	综合判定：合格。	
9	GX-B1417/22-P-231476	2024. 1. 7	综合判定：合格。	

10	GX-B1417/22-P-231477	2024. 1. 7	综合判定：合格。	
11	GX-B1417/22-P-231478	2024. 1. 7	综合判定：合格。	

12	GX-B1417/22-P-231479	2024. 1. 7	综合判定：合格。	 <p>A worker wearing a grey jacket with a logo, a red helmet, and dark pants is kneeling on a snowy and icy ground. The worker is focused on a piece of equipment or a task on the ground. The background shows a large piece of machinery, possibly a truck or a heavy vehicle, partially covered in snow. The date '2023.12.14' is visible in the bottom right corner of the photo.</p>
13	GX-B1417/22-P-231480	2024. 1. 7	综合判定：合格。	 <p>A worker wearing a black jacket, a red helmet, and dark pants is standing next to a white truck. The worker is looking up at the side of the truck, possibly inspecting it. The truck has '国家能源集团 CHN ENERGY' and '定载 1 人' written on it. A red and white striped traffic cone is visible on the ground next to the truck. The date '2023.12.15' is visible in the bottom right corner of the photo.</p>

14	GX-B1417/22-P-231481	2024. 1. 7	综合判定：合格。	
15	GX-B1417/22-P-231482	2024. 1. 7	综合判定：合格。	

16	GX-B1417/22-P-231483	2024. 1. 7	综合判定：合格。	 <p>2023.12.15</p>
17	GX-B1417/22-P-231484	2024. 1. 7	综合判定：合格。	 <p>2023.12.15</p>

18	GX-B1417/22-P-231485	2024. 1. 7	综合判定：合格。	
19	GX-B1417/22-P-231486	2024. 1. 7	综合判定：合格。	

20	GX-B1417/22-P-231487	2024. 1. 7	综合判定：合格。	
21	GX-B1417/22-P-231488	2024. 1. 7	综合判定：合格。	

22	GX-B1417/22-P-231489	2024. 1. 7	综合判定：合格。			
23	GX-B1417/22-P-231490	2024. 1. 7	综合判定：合格。			

24	GX-B1417/22-P-231491	2024. 1. 7	综合判定：合格。		
25	GX-B1417/22-P-231492	2024. 1. 7	综合判定：合格。		

26	GX-B1417/22-P-231493	2024. 1. 7	综合判定：合格。			
27	GX-B1417/22-P-231494	2024. 1. 7	综合判定：合格。			

28	GX-B1417/22-P-231495	2024. 1. 7	综合判定：合格。	
29	GX-B1417/22-P-231496	2024. 1. 7	综合判定：合格。	

30	GX-B1417/22-P-231497	2024. 1. 7	综合判定：合格。	 A photograph showing a person in a light-colored jacket and dark pants operating a floor cleaning machine in a warehouse. The machine is white and yellow, with the number '3554' visible on its side. The floor is wet and reflective. A date stamp '2023.12.17' is visible in the bottom right corner of the image.
31	GX-B1417/22-P-231498	2024. 1. 7	综合判定：合格。	 A photograph showing a person in a light-colored jacket and dark pants operating a floor cleaning machine in a warehouse. The machine is white and yellow, with the number '3555' visible on its side. The floor is wet and reflective. A date stamp '2023.12.17' is visible in the bottom right corner of the image.

32	GX-B1417/22-P-231499	2024. 1. 7	综合判定：合格。	
33	GX-B1417/22-P-231500	2024. 1. 7	综合判定：合格。	

34	GX-B1417/22-P-231501	2024. 1. 7	综合判定：合格。	 <p>A worker wearing a grey jacket and a red hard hat is standing next to a piece of machinery, possibly a forklift or a similar industrial vehicle. The worker is looking towards the machinery. The background shows an industrial setting with a building and some equipment. A date stamp '2023.12.14' is visible in the bottom right corner of the image.</p>
35	GX-B1417/22-P-231502	2024. 1. 7	综合判定：合格。	 <p>A worker wearing a grey jacket and a red hard hat is kneeling on a snowy surface, inspecting a piece of machinery. The worker's jacket has the logo '中检公信' (China Inspection and Certification) on the back. The worker is looking down at the machinery. The background shows a snowy industrial setting. A date stamp '2023.12.14' is visible in the bottom right corner of the image.</p>

36	GX-B1417/22-P-231503	2024. 1. 7	综合判定：合格。	
37	GX-B1417/22-P-231504	2024. 1. 7	综合判定：合格。	

38	GX-B1417/22-P-231505	2024. 1. 7	综合判定：合格。	
39	GX-B1417/22-P-231506	2024. 1. 7	综合判定：合格。	

40	GX-B1417/22-P-231507	2024. 1. 7	综合判定：合格。	 <p>2023.12.17</p>
41	GX-B1417/22-P-231508	2024. 1. 7	综合判定：合格。	 <p>2023.12.17</p>

42	GX-B1417/22-P-231509	2024. 1. 7	综合判定：合格。	
43	GX-B1417/22-P-231510	2024. 1. 7	综合判定：合格。	

44	GX-B1417/22-P-231511	2024. 1. 7	综合判定：合格。	
45	GX-B1417/22-P-231512	2024. 1. 7	综合判定：合格。	

46	GX-B1417/22-P-231513	2024. 1. 7	综合判定：合格。	 <p>2023.12.14</p>
47	GX-B1417/22-P-231514	2024. 1. 7	综合判定：合格。	 <p>2023.12.17</p>

48	GX-B1417/22-P-231515	2024. 1. 7	综合判定：合格。	 <p>2023.12.14</p>
49	GX-B1417/22-P-231516	2024. 1. 7	综合判定：合格。	 <p>2023.12.14</p>

50	GX-B1417/22-P-231517	2024. 1. 7	综合判定：合格。	
51	GX-B1417/22-P-231518	2024. 1. 7	综合判定：合格。	

52	GX-B1417/22-P-231519	2024. 1. 7	综合判定：合格。	
53	GX-B1417/22-P-231520	2024. 1. 7	综合判定：合格。	

54	GX-B1417/22-P-231521	2024. 1. 7	综合判定：合格。	 <p>2023.12.16</p>
55	GX-B1417/22-P-231522	2024. 1. 7	综合判定：合格。	 <p>2023.12.16</p>

56	GX-B1417/22-P-231523	2024. 1. 7	综合判定：合格。	 A worker wearing a red hard hat and a dark, heavy jacket is seen from behind, working on the back of a white truck. The truck has a yellow and red stripe on its rear panel, with the number '3' visible. The worker is holding a tool or part. The background shows an indoor industrial setting with other vehicles and equipment. A timestamp '2023.12.16' is visible in the bottom right corner of the photo.
57	GX-B1417/22-P-231524	2024. 1. 7	综合判定：合格。	 A worker wearing a red hard hat and a dark jacket is working on the back of a white truck. The worker is holding a tool and appears to be focused on a task. The truck is parked in a factory or workshop setting with green and yellow floor markings. A timestamp '2023.12.16' is visible in the bottom right corner of the photo.

58	GX-B1417/22-P-231525	2024. 1. 7	综合判定：合格。	 <p>2023.12.16</p>
59	GX-B1417/22-P-231526	2024. 1. 7	综合判定：合格。	 <p>2023.12.16</p>

60	GX-B1417/22-P-231527	2024. 1. 7	综合判定：合格。	 <p>2023.12.16</p>
61	GX-B1417/22-P-231528	2024. 1. 7	综合判定：合格。	 <p>2023.12.16</p>

62	GX-B1417/22-P-231529	2024. 1. 7	综合判定：合格。	
63	GX-B1417/22-P-231530	2024. 1. 7	综合判定：合格。	

64	GX-B1417/22-P-231531	2024. 1. 7	综合判定：合格。	
65	GX-B1417/22-P-231532	2024. 1. 7	综合判定：合格。	

66	GX-B1417/22-P-231533	2024. 1. 7	综合判定：合格。	 A photograph showing two workers wearing red hard hats and dark jackets. They are standing next to a white truck, looking at something on the side of the vehicle. The date '2023.12.17' is visible in the bottom right corner of the photo.
67	GX-B1417/22-P-231829	2024. 1. 7	综合判定：合格。	 A photograph showing a worker in a red hard hat and dark jacket working on a white truck. The worker is positioned in the truck bed, which contains a large gas cylinder. The license plate 'X-TK008206' is visible on the side of the truck. The date '2023.12.15' is visible in the bottom right corner of the photo.

68	GX-B1417/22-P-231830	2024. 1. 7	综合判定：合格。	
69	GX-B1417/22-P-231831	2023. 1. 8	综合判定：合格。	

70	GX-B1417/22-P-231832	2023. 1. 8	综合判定：合格。	 <p>2023.12.15</p>
71	GX-B1559/22-P-231857	2024. 1. 8	综合判定：合格	 <p>2023.12.17</p>

72	GX-B1559/22-P-23155	2023. 1. 8	所检项目合格。	
73	GX-B1559/22-P-23156	2023. 1. 8	所检项目合格。	

74	GX-B1559/22-P-23157	2023. 1. 8	所检项目合格。	 <p>2023.12.14</p>
75	GX-B1559/22-P-23158	2023. 1. 8	所检项目合格。	 <p>2023.12.15</p>

76	GX-B1559/22-P-23159	2023. 1. 8	所检项目合格。	
77	GX-B1559/22-P-23160	2023. 1. 8	所检项目合格。	

78	GX-B1559/22-P-23161	2023. 1. 8	所检项目合格。		
79	GX-B1559/22-P-23162	2023. 1. 8	所检项目合格。		

80	GX-B1559/22-P-23163	2023. 1. 8	所检项目合格。		
81	GX-B1559/22-P-23164	2023. 1. 8	所检项目合格。		

82	GX-B1559/22-P-23165	2023. 1. 8	所检项目合格。	
83	GX-B1559/22-P-23166	2023. 1. 8	所检项目合格。	

84	GX-B1559/22-P-23182	2024. 1. 9	所检项目合格。	 <p>2023.12.27</p>
85	GX-B1559/22-P-23183	2024. 1. 9	所检项目合格。	 <p>2023.12.27</p>

86	GX-B1499/23-P-23122	2024年1月9日	所检项目合格。			
87	GX-B1499/23-P-23123	2024年1月9日	所检项目合格。			

88	GX-B1499/23-P-23124	2024年1月9日	所检项目合格。	 <p>2023.12.25</p>
89	GX-B1322/21-P-23097~23099	2024. 1. 11	所检项目合格。	 <p>2023.12.9</p>

90	GX-B1310/21-P-23168	2024. 1. 11	符合标准要求	 <p>2023.12.9</p>
91	GX-B1427/21-P-23029	2024. 1. 11	符合标准要求	 <p>2023.12.9</p>

92	GX-B1451/20-P-23015~23016	2024. 1. 12	本次共检开关设备2台，2台开关设备所检项目合格。	 <p>2023 12 10</p>
93	GX-B1451/20-P-23017~23018	2024. 1. 12	本次共检高压真空配电装置2台，2台高压真空配电装置所检项目合格。	 <p>2023 12 10</p>

94	GX-B1451/20-P-23009~23014	2024. 1. 12	本次共检高压真空配电装置6台，6台高压真空配电装置所检项目合格。	 A photograph showing a worker in a grey jacket and red helmet inspecting a high-voltage vacuum circuit breaker. The worker is kneeling and looking at the internal components of the device. The device is red and has a black door open. The background shows other similar devices in a room. A timestamp '2023.12.09' is visible in the bottom right corner of the photo.
----	---------------------------	-------------	----------------------------------	--