

序号	报告编号	发布日期	结论	影像资料
73	GX-B1428/21-3-23078	2023. 12. 22	无缺陷迹痕显示	
74	GX-B1310/21-3-23285	2023. 12. 22	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷	

75	GX-B1428/21-3-23079	2023. 12. 22	无缺陷迹痕显示	
76	GX-B1310/21-3-23286	2023. 12. 22	未发现超过 $\phi 2\text{mm}$ 当量直径的缺陷	


77	GX-B1428/21-3-23074	2023. 12. 22	无缺陷迹痕显示	 A photograph showing a worker in a red jacket and white hard hat inside a tunnel. The worker is holding a flashlight that illuminates a large pipe. A date stamp '2023.12.14' is visible in the bottom right corner of the photo.
78	GX-B1310/21-3-23281	2023. 12. 22	未发现超过 $\phi 2\text{mm}$ 当量直径的缺陷	 A photograph showing a worker in a red jacket and white hard hat inside a tunnel. The worker is holding a flashlight that illuminates a large pipe. A date stamp '2023.12.14' is visible in the bottom right corner of the photo.

79	GX-B1428/21-3-23075	2023. 12. 22	无缺陷迹痕显示	
80	GX-B1310/21-3-23282	2023. 12. 22	未发现超过 $\phi 2\text{mm}$ 当量直径的缺陷	

81	GX-B1428/21-3-23076	2023. 12. 22	无缺陷迹痕显示	
82	GX-B1310/21-3-23283	2023. 12. 22	未发现超过 $\phi 2\text{mm}$ 当量直径的缺陷	

83	GX-B1428/21-3-23077	2023. 12. 22	无缺陷迹痕显示	
84	GX-B1310/21-3-23284	2023. 12. 22	未发现超过 $\phi 2\text{mm}$ 当量直径的缺陷	

85	GX-B1559/22-3-23007	2023.12.28	所检项目合格。	
86	GX-B1559/22-3-23008	2023.12.28	所检项目合格。	

87	GX-B1559/22-3-23009	2023.12.28	所检项目合格。	 <p>2023.12.26</p>
88	GX-B1559/22-3-23010	2023.12.28	所检项目合格。	 <p>2023.12.26</p>

89	GX-B1559/22-3-23011	2023.12.28	所检项目合格。	
90	GX-B1559/22-3-23012	2023.12.28	所检项目合格。	

91	GX-B1559/22-3-23013	2023. 12. 28	所检项目合格。	 <p>2023.12.26</p>
92	GX-B1559/22-3-23014	2023. 12. 28	所检项目合格。	 <p>2023.12.26</p>

93	GX-B1559/22-3-23015	2023.12.28	所检项目合格。	 <p>2023.12.26</p>
94	GX-B1559/22-3-23016	2023.12.28	所检项目合格。	 <p>2023.12.26</p>

95	GX-B1559/22-3-23017	2023. 12. 28	所检项目合格。	 <p>2023.12.26</p>
96	GX-B1559/22-3-23018	2023. 12. 28	所检项目合格。	 <p>2023.12.26</p>

97	GX-B1559/22-3-23019	2023.12.28	所检项目合格。	
98	GX-B1328/20-3-23261	2023.12.28		
99	GX-B1328/20-3-23262	2023.12.28		
100	GX-B1328/20-3-23267	2023.12.28		
101	GX-B1328/20-3-23268	2023.12.28		

102	GX-B1328/20-3-23263	2023.12.28	所检项目	
103	GX-B1328/20-3-23264	2023.12.28	本次共检验电器6支，6支验电器合格。	

104	GX-B1328/20-3-23265	2023.12.28	本次共检便携式接地和接地短路装置10套，10套便携式接地和接地短路装置合格。	
105	GX-B1328/20-3-23266	2023.12.28	本次共检绝缘杆4套，4套绝缘杆所检项目合格。	

106	GX-B1500/21-3-23085	2023年12月26日	综合判定：合格。	
107	GX-B1424/20-3-23048	2023年12月31日	依据NB/T 10176-2019单轨吊车综合判定合格。	