

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|----|---------------------|-------------|----------------------------|---|
| 31 | GX-B1328/20-4-23225 | 2024. 1. 16 | 本次共检绝缘手套40只，40只所检项目合格。 |  |
| 32 | GX-B1328/20-4-23226 | 2024. 1. 16 | 本次共检绝缘鞋40只，40只所检项目合格。 |  |
| 33 | GX-B1328/20-4-23227 | 2024. 1. 16 | 本次共检验电器16支，16支所检项目合格。 |  |
| 34 | GX-B1328/20-4-23228 | 2024. 1. 16 | 本次共检便携式短路接地线16套，16套所检项目合格。 |  |

| | | | | |
|----|---------------------------|-------------|--------------------------|--|
| 35 | GX-B1328/20-4-23229 | 2024. 1. 16 | 所检项目合格。 |  |
| 36 | GX-B1321/20-4-24001~24006 | 2024. 1. 18 | 本次共检电力电缆6条，6条电力电缆所检项目合格。 |  |
| 37 | GX-B1328/20-4-23230 | 2024. 1. 19 | 本次共检绝缘手套2只，2只所检项目合格。 |  |
| 38 | GX-B1328/20-4-23231 | 2024. 1. 19 | 本次共检绝缘鞋2只，2只所检项目合格。 |  |

| | | | | |
|----|---------------------|-------------|----------|---|
| 39 | GX-B1328/20-4-23232 | 2024. 1. 19 | 所检项目合格。 |  |
| 40 | GX-B1301/23-4-24001 | 2024. 1. 22 | 综合判定:合格。 |  |
| 41 | GX-B1301/23-4-23008 | 2024. 1. 22 | 综合判定:合格。 |  |
| 42 | GX-B1302/21-4-23002 | 2024. 1. 22 | 综合判定:合格。 |  |

| | | | | |
|----|---------------------|-------------|---------------|--|
| 43 | GX-B1300/23-4-23019 | 2024. 1. 22 | 综合判定:合格。 |  |
| 44 | GX-B1300/23-4-23018 | 2024. 1. 22 | 综合判定:合格。 |  |
| 45 | GX-B1354/20-4-24001 | 2024. 1. 22 | 电网接地电容电流符合规定。 |  |
| 46 | GX-B1358/21-4-24001 | 2024. 1. 22 | 所检项目合格。 |  |

| | | | | |
|----|---------------------|-------------|----------|---|
| 47 | GX-B1301/23-4-23008 | 2024. 1. 23 | 综合判定:合格。 |  A large green industrial machine, possibly a motor or generator, is shown in a factory setting. The machine is surrounded by a green safety fence. A date stamp '2023-11-22' is visible in the bottom right corner of the image. |
| 48 | GX-B1302/21-4-23002 | 2024. 1. 23 | 综合判定:合格。 |  Two workers wearing yellow hard hats and light-colored shirts are standing in a factory. They are looking at a document held by one of the workers. A date stamp '2023-11-21' is visible in the bottom right corner of the image. |
| 49 | GX-B1300/23-4-23019 | 2024. 1. 23 | 综合判定:合格。 |  A close-up view of a large industrial machine with a prominent red frame. The machine appears to be a part of a manufacturing process. A date stamp '2023-11-22' is visible in the bottom right corner of the image. |
| 50 | GX-B1300/23-4-23018 | 2024. 1. 23 | 综合判定:合格。 |  A worker wearing a yellow hard hat and a light-colored shirt is operating a large green industrial machine in a factory. The machine is surrounded by a blue safety fence. A date stamp '2023-11-21' is visible in the bottom right corner of the image. |

| | | | | | | |
|----|---------------------|-------------|-------------------------|--|--|--|
| 51 | GX-B1328/20-4-23218 | 2024. 1. 23 | 本次共检绝缘鞋250只，250只所检项目合格。 | |  | |
| 52 | GX-B1328/20-4-23219 | 2024. 1. 23 | 本次共检绝缘鞋40只，40只所检项目合格。 | |  | |
| 53 | GX-B1328/20-4-23224 | 2024. 1. 23 | 本次共检绝缘鞋210只，210只所检项目合格。 | |  | |
| 54 | GX-B1328/20-4-23220 | 2024. 1. 23 | 本次共检验电器160支，160支所检项目合格。 | |  | |

| | | | | |
|----|---------------------|-------------|--------------------------|--|
| 55 | GX-B1328/20-4-23222 | 2024. 1. 23 | 本次共检绝缘杆10只，10只所检项目合格。 |  |
| 56 | GX-B1328/20-4-23216 | 2024. 1. 23 | 本次共检绝缘手套250只，250只所检项目合格。 |  |
| 57 | GX-B1328/20-4-23217 | 2024. 1. 23 | 本次共检绝缘手套108只，108只所检项目合格。 |  |
| 58 | GX-B1328/20-4-23223 | 2024. 1. 23 | 本次共检绝缘手套192只，192只所检项目合格。 |  |

| | | | | |
|----|---------------------|-------------|---------------------------|--|
| 59 | GX-B1328/20-4-23221 | 2024. 1. 23 | 本次共检短路接地线132套，132套所检项目合格。 |  |
| 60 | GX-B1517/20-4-24002 | 2024. 1. 24 | 综合判定：合格 |  |
| 61 | GX-B1517/20-4-24003 | 2024. 1. 24 | 综合判定：合格 |  |
| 62 | GX-B1517/20-4-24004 | 2024. 1. 24 | 综合判定：合格 |  |

| | | | | | | |
|----|---------------------|-------------|---------|--|---|--|
| 63 | GX-B1517/20-4-24005 | 2024. 1. 24 | 综合判定：合格 | |  | |
| 64 | GX-B1517/20-4-24006 | 2024. 1. 24 | 综合判定：合格 | |  | |