

| 序号 | 报告编号                      | 发布日期        | 结论                             | 影像资料   |
|----|---------------------------|-------------|--------------------------------|--|
| 90 | GX-B1354/20-5-23020       | 2024. 1. 17 | 电网接地电容电流符合规定。                  |   |
| 91 | GX-B1323/21-5-24003~24004 | 2024. 1. 17 | 本次共检三相交流电动机2台，2台三相交流电动机所检项目合格。 |  |

|    |                           |             |                                |  |
|----|---------------------------|-------------|--------------------------------|--|
| 92 | GX-B1495/20-5-24001~24003 | 2024. 1. 17 | 本次共检高压防爆开关3台，3台高压防爆开关所检项目合格。   |   |
| 93 | GX-B1323/21-5-24001~24002 | 2024. 1. 17 | 本次共检三相交流电动机2台，2台三相交流电动机所检项目合格。 |  |

|    |                           |             |                            |  |  |  |
|----|---------------------------|-------------|----------------------------|--|--|--|
| 94 | GX-B1321/20-5-24011~24020 | 2024. 1. 17 | 本次共检电力电缆10条，10条电力电缆所检项目合格。 |  |   |  |
| 95 | GX-B1495/20-5-24004~24010 | 2024. 1. 17 | 本次共检高压开关柜7台，7台高压开关柜所检项目合格。 |  |  |  |

|    |                     |             |          |  |
|----|---------------------|-------------|----------|--|
| 96 | GX-B1310/21-5-24002 | 2024. 1. 17 | 符合标准要求。  |   |
| 97 | GX-B1428/21-5-24001 | 2024. 1. 17 | 无缺陷迹痕显示。 |  |

|    |                     |             |                                       |  |
|----|---------------------|-------------|---------------------------------------|--|
| 98 | GX-B1301/23-5-24002 | 2024. 1. 19 | 综合判定:合格。                              |   |
| 99 | GX-B1598/21-5-24001 | 2024/1/19   | 实测钢丝绳有效截面积损失百分比最大为2.07%，小于5%为正常。<br>。 |  |

|     |                     |           |  |  |
|-----|---------------------|-----------|--|--|
| 100 | GX-B1598/21-5-24002 | 2024/1/19 | 实测钢丝绳有效截面积损失百分比最大为2.04%，小于5%为正常。<br>。  |   |
| 101 | GX-B1598/21-5-24003 | 2024/1/19 | 实测钢丝绳有效截面积损失百分比最大为2.31%，小于5%为正常。<br>。。 |  |

|     |                     |           |                                       |  |
|-----|---------------------|-----------|---------------------------------------|--|
| 102 | GX-B1598/21-5-24004 | 2024/1/19 | 实测钢丝绳有效截面积损失百分比最大为1.19%，小于5%为正常。<br>。 |   |
| 103 | GX-B1598/21-5-24005 | 2024/1/19 | 实测钢丝绳有效截面积损失百分比最大为3.16%，小于5%为正常。<br>。 |  |

|     |                     |           |                                       |  |  |
|-----|---------------------|-----------|---------------------------------------|--|--|
| 104 | GX-B1598/21-5-24006 | 2024/1/19 | 实测钢丝绳有效截面积损失百分比最大3.88%，小于5%为正常。<br>。  |  |   |
| 105 | GX-B1598/21-5-24007 | 2024/1/19 | 实测钢丝绳有效截面积损失百分比最大为3.75%，小于5%为正常。<br>。 |  |  |

|     |                     |           |                                       |  |  |  |
|-----|---------------------|-----------|---------------------------------------|--|--|--|
| 106 | GX-B1598/21-5-24008 | 2024/1/19 | 实测钢丝绳有效截面积损失百分比最大为3.44%，小于5%为正常。<br>。 |  |   |  |
| 107 | GX-B1598/21-5-24009 | 2024/1/19 | 实测钢丝绳有效截面积损失百分比最大为2.55%，小于5%为正常。<br>。 |  |  |  |

|     |                     |           |        |  |  |
|-----|---------------------|-----------|--------|--|--|
| 108 | GX-B1380/20-5-24001 | 2024/1/21 | 所检项目合格 |  |   |
| 109 | GX-B1380/20-5-24002 | 2024/1/21 | 所检项目合格 |  |  |

|     |                     |           |        |  |   |  |
|-----|---------------------|-----------|--------|--|---|--|
| 110 | GX-B1380/20-5-24003 | 2024/1/21 | 所检项目合格 |  |  A worker wearing a red hard hat and a blue jacket is inspecting a metal structure, possibly a cage or a piece of machinery, in an industrial setting. The worker is holding a tool or a light. The date 2023/1/13 is visible in the bottom right corner of the image.                                   |  |
| 111 | GX-B1380/20-5-24004 | 2024/1/21 | 所检项目合格 |  |  Two workers wearing hard hats (one yellow, one red) and jackets are inspecting a metal structure, possibly a cage or a piece of machinery, in an industrial setting. The workers are standing on a platform or a set of stairs. The date 2023/1/13 is visible in the bottom right corner of the image. |  |

|     |                           |             |                                |   |
|-----|---------------------------|-------------|--------------------------------|---|
| 112 | GX-B1451/20-5-23250~23253 | 2024. 1. 21 | 本次共检继电保护装置4台，4台继电保护装置所检项目合格。   |  |
| 113 | GX-B1319/21-5-23269~23277 | 2024. 1. 21 | 本次共检高压交流断路器9台，9台高压交流断路器所检项目合格。 |  |

|     |                           |             |                                |   |
|-----|---------------------------|-------------|--------------------------------|---|
| 114 | GX-B1319/21-5-23278~23282 | 2024. 1. 21 | 本次共检高压交流断路器5台，5台高压交流断路器所检项目合格。 |  |
| 115 | GX-B1451/20-5-23241~23249 | 2024. 1. 21 | 本次共检高压开关柜9台，9台高压开关柜所检项目合格。     |  |

|     |                           |             |                                  |  |
|-----|---------------------------|-------------|----------------------------------|--|
| 116 | GX-B1319/21-5-23225~23245 | 2024. 1. 21 | 本次共检高压交流断路器21台，21台高压交流断路器所检项目合格。 |   |
| 117 | GX-B1319/21-5-23246~23268 | 2024. 1. 21 | 本次共检高压交流断路器23台，23台高压交流断路器所检项目合格。 |  |


|     |                           |             |                              |  |  |
|-----|---------------------------|-------------|------------------------------|--|--|
| 118 | GX-B1451/20-5-23197~23219 | 2024. 1. 21 | 本次共检高压开关柜23台，23台高压开关柜所检项目合格。 |  |   |
| 119 | GX-B1451/20-5-23220~23240 | 2024. 1. 21 | 本次共检高压开关柜21台，21台高压开关柜所检项目合格。 |  |  |

|     |                           |             |                                  |  |
|-----|---------------------------|-------------|----------------------------------|--|
| 120 | GX-B1322/21-5-23088~23099 | 2024. 1. 21 | 本次共检电力电缆12条，12条电力电缆所检项目合格。       |   |
| 121 | GX-B1319/21-5-23156~23181 | 2024. 1. 21 | 本次共检高压交流断路器26台，26台高压交流断路器所检项目合格。 |  |

|     |                           |             |                              |  |
|-----|---------------------------|-------------|------------------------------|--|
| 122 | GX-B1451/20-5-23129~23153 | 2024. 1. 21 | 本次共检高压开关柜25台，25台高压开关柜所检项目合格。 |   |
| 123 | GX-B1322/21-5-23100~23101 | 2024. 1. 21 | 本次共检电力电缆2条，2条电力电缆所检项目合格。     |  |

|     |                           |             |                                  |  |
|-----|---------------------------|-------------|----------------------------------|--|
| 124 | GX-B1451/20-5-23154~23177 | 2024. 1. 21 | 本次共检高压开关柜24台，24台高压开关柜所检项目合格。     |  <p>2023/12/29</p>  |
| 125 | GX-B1319/21-5-23183~23206 | 2024. 1. 21 | 本次共检高压交流断路器24台，24台高压交流断路器所检项目合格。 |  <p>2023/12/29</p> |

|     |                           |             |                                  |  |
|-----|---------------------------|-------------|----------------------------------|--|
| 126 | GX-B1319/21-5-23207~23224 | 2024. 1. 21 | 本次共检高压交流断路器18台，18台高压交流断路器所检项目合格。 |   |
| 127 | GX-B1451/20-5-23179~23196 | 2024. 1. 21 | 本次共检高压开关柜18台，18台高压开关柜所检项目合格。     |  |

|     |                     |              |          |  |
|-----|---------------------|--------------|----------|--|
| 128 | GX-B1310/21-5-23321 | 2024. 01. 19 | 符合标准要求。  |   |
| 129 | GX-B1427/21-5-23026 | 2024. 01. 19 | 无缺陷磁痕显示。 |  |