


序号	报告编号	发布日期	结论	影像资料
53	GX-B1323/21-6-23250~23253	2024/1/16	本次共检三相交流电动机4台，4台三相交流电动机所检项目合格。	
54	GX-B1328/20-6-23163	2024/1/16	本次共检绝缘手套32只，32只绝缘手套所检项目合格。	

55	GX-B1328/20-6-23164	2024/1/16	<p>本次共检全橡胶绝缘胶靴32只，32只全橡胶绝缘胶靴所检项目合格。</p>	 <p>A photograph showing several workers in blue uniforms and red hard hats inspecting a large number of black rubber boots. The boots are arranged in rows on the ground. A date stamp '2023.12.26' is visible in the bottom right corner.</p>
56	GX-B1328/20-6-23165	2024/1/16	<p>本次共检验电器3支，3支验电器所检项目合格。</p>	 <p>A photograph showing workers in blue uniforms and red hard hats inspecting electrical testing equipment. The equipment is laid out on the ground. A date stamp '2023.12.26' is visible in the bottom right corner.</p>
57	GX-B1328/20-6-23166	2024/1/16	<p>本次共检便携式接地和接地短路装置3套，3套便携式接地和接地短路装置所检项目合格。</p>	 <p>A photograph showing workers in blue uniforms and red hard hats inspecting portable grounding and short-circuiting devices. The devices are laid out on the ground. A date stamp '2023.12.26' is visible in the bottom right corner.</p>

58	GX-B1310/21-6-23186	2024/1/16	符合标准要求	
59	GX-B1310/21-6-23187	2024/1/16	符合标准要求	
60	GX-B1424/20-6-24001	2024/1/17	依据NB/T 10176-2019单轨吊车所检项目合格。	

61	GX-B1424/20-6-24002	2024/1/17	依据NB/T 10176-2019单轨吊车所检项目合格。	 <p>2024 01 04</p>
62	GX-B1383/21-6-24001	2024/1/17	综合判定合格	 <p>2024 01 04</p>
63	GX-B1383/21-6-24002	2024/1/17	综合判定合格	 <p>2024 01 04</p>

64	GX-B1303/21-6-23026	2024/1/17	综合判定：合格。	
65	GX-B1303/21-6-23027	2024/1/17	综合判定：合格。	
66	GX-B1598/21-6-23087	2024/1/17	实测钢丝绳有效截面积损失百分比最大为3.52%，小于5%为正常。	

67	GX-B1598/21-6-23088	2024/1/17	实测钢丝绳有效截面积损失百分比最大为3.30%，小于5%为正常	
68	GX-B1380/20-6-23041	2024/1/17	所检项目合格。	
69	GX-B1382/21-6-23037	2024/1/17	合格。	

70	GX-B1321/20-6-23789~23798	2024/1/16	所检项目合格	 <p>2023 12 26</p>
71	GX-B1495/20-6-231376~231383	2024/1/17	所检项目合格	 <p>2023 12 26</p>
72	GX-B1520/20-6-24003	2024/1/17	综合判定合格	 <p>2024 01 06</p>

73	GX-B1520/20-6-24001	2024/1/17	综合判定合格	 <p>2024.01.06</p>
74	GX-B1520/20-6-24002	2024/1/17	综合判定合格	 <p>2024.01.06</p>
75	GX-B1598/21-6-23089	2024/1/18	实测钢丝绳有效截面积损失百分比最大为1.76%，小于5%为正常。	 <p>2023.12.29</p>

76	GX-B1598/21-6-23090	2024/1/18	实测钢丝绳有效截面积损失百分比最大为2.32%，小于5%为正常。			
77	GX-B1598/21-6-23091	2024/1/18	实测钢丝绳有效截面积损失百分比最大为1.96%，小于5%为正常。			
78	GX-B1598/21-6-23092	2024/1/18	实测钢丝绳有效截面积损失百分比最大为1.81%，小于5%为正常。			

79	GX-B1598/21-6-23093	2024/1/18	实测钢丝绳有效截面积损失百分比最大为1.82%，小于5%为正常。	
80	GX-B1598/21-6-23094	2024/1/18	实测钢丝绳有效截面积损失百分比最大为2.24%，小于5%为正常。	
81	GX-B1310/21-6-23188	2024/1/18	符合标准要求	

82	GX-B1427/21-6-23096	2024/1/18	符合标准要求	
83	GX-B1424/20-6-23025	2024/1/18	依据NB/T 10176-2019单轨吊车综合判定合格。	
84	GX-B1321/20-6-23799~23804	2024/1/19	所检项目合格	

85	GX-B1321/20-6-23805~23811	2024/1/19	所检项目合格	
86	GX-B1301/23-6-23008	2024/1/19	综合判定合格	
87	GX-B1307/20-6-23069	2024/1/22	综合判定：合格。	

88	GX-B1520/20-6-24013	2024/1/23	综合判定：合格。	
89	GX-B1520/20-6-24014	2024/1/23	综合判定：合格。	
90	GX-B1520/20-6-24012	2024/1/23	综合判定：合格。	

91	GX-B1520/20-6-24011	2024/1/23	综合判定：合格。	
----	---------------------	-----------	----------	---