


| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|----|---------------------|----------|----------|--|
| 5 | GX-B1307/20-1-24001 | 2024/2/7 | 综合判定：合格。 |  |
| 6 | GX-B1307/20-1-24002 | 2024/2/7 | 综合判定：合格。 |  |
| 7 | GX-B1307/20-1-24003 | 2024/2/7 | 综合判定：合格。 |  |

| | | | | |
|----|---------------------------|----------|---------------------------|--|
| 8 | GX-B1307/20-1-24004 | 2024/2/7 | 综合判定：合格。 |  |
| 9 | GX-B1322/21-1-24093~24100 | 2024/2/8 | 本次共检验电力电缆8条，8条电力电缆所检项目合格。 |  |
| 10 | GX-B1322/21-1-24101~24105 | 2024/2/8 | 本次共检验电力电缆5条，5条电力电缆所检项目合格。 |  |

| | | | | |
|----|---------------------------|----------|---------------------------|--|
| 11 | GX-B1322/21-1-24106~24110 | 2024/2/8 | 本次共检验电力电缆5条，5条电力电缆所检项目合格。 |  |
| 12 | GX-B1451/20-1-24089~24098 | 2024/2/7 | 所检项目合格 |  |
| 13 | GX-B1451/20-1-24099~24116 | 2024/2/7 | 所检项目合格 |  |

| | | | | |
|----|---------------------------|----------|--------|--|
| 14 | GX-B1451/20-1-24117~24135 | 2024/2/7 | 所检项目合格 |  |
| 15 | GX-B1451/20-1-24136~24149 | 2024/2/7 | 所检项目合格 |  |
| 16 | GX-B1451/20-1-24150~24154 | 2024/2/7 | 所检项目合格 |  |

| | | | | |
|----|---------------------------|----------|--------|--|
| 17 | GX-B1451/20-1-24155~24163 | 2024/2/7 | 所检项目合格 |  |
| 18 | GX-B1451/20-1-24164~24174 | 2024/2/7 | 所检项目合格 |  |
| 19 | GX-B1451/20-1-24175~24190 | 2024/2/7 | 所检项目合格 |  |

| | | | | |
|----|---------------------------|----------|--------|--|
| 20 | GX-B1451/20-1-24191~24200 | 2024/2/7 | 所检项目合格 |  |
| 21 | GX-B1451/20-1-24201~24215 | 2024/2/7 | 所检项目合格 |  |
| 22 | GX-B1451/20-1-24216~24225 | 2024/2/7 | 所检项目合格 |  |

| | | | | |
|----|---------------------------|----------|--------|--|
| 23 | GX-B1451/20-1-24226~24227 | 2024/2/7 | 所检项目合格 |  |
| 24 | GX-B1322/21-1-24030~24044 | 2024/2/8 | 所检项目合格 |  |
| 25 | GX-B1322/21-1-24045~24050 | 2024/2/8 | 所检项目合格 |  |

| | | | | |
|----|---------------------------|----------|--------|--|
| 26 | GX-B1322/21-1-24051~24055 | 2024/2/8 | 所检项目合格 |  |
| 27 | GX-B1322/21-1-24056~24067 | 2024/2/8 | 所检项目合格 |  |
| 28 | GX-B1322/21-1-24068~24078 | 2024/2/8 | 所检项目合格 |  |

| | | | | |
|----|---------------------------|------------|---------|---|
| 29 | GX-B1322/21-1-24079~24090 | 2024/2/8 | 所检项目合格 |  A worker in an orange safety suit and helmet is working on a piece of equipment. The date stamp '2024.1.18' is visible at the bottom of the photo. |
| 30 | GX-B1309/21-1-24001 | 2024. 2. 7 | 所检项目合格 |  A worker in an orange safety suit and helmet is walking on a narrow metal walkway in a dark tunnel. The date stamp '2024.1.24' is visible at the bottom of the photo. |
| 31 | GX-B1500/21-1-24001 | 2024. 2. 7 | 综合判定：合格 |  A worker in an orange safety suit and helmet is working on a large green industrial machine. The date stamp '2024.1.24' is visible at the bottom of the photo. |

| | | | | | |
|----|---------------------|------------|---------|--|--|
| 32 | GX-B1500/21-1-24002 | 2024. 2. 7 | 综合判定：合格 |  | |
| 33 | GX-B1500/21-1-24003 | 2024. 2. 7 | 综合判定：合格 |  | |
| 34 | GX-B1428/21-1-24012 | 2024. 2. 7 | 无缺陷痕迹显示 |  | |

| | | | | |
|----|---------------------------|------------|---------------------------------------|--|
| 35 | GX-B1428/21-1-24013 | 2024. 2. 7 | 无缺陷迹痕显示 |  |
| 36 | GX-B1451/20-1-24061~24066 | 2024. 2. 7 | 本次共检高压开关设备6台， 6台高压开关设备所检项目合格 |  |
| 37 | GX-B1451/20-1-24067~24088 | 2024. 2. 7 | 本次共检高压开关设备 22台，22台高压开关设备所 检项目合格 |  |

| | | | | |
|----|---------------------------|------------|----------------------------|--|
| 38 | GX-B1322/21-1-24030~24044 | 2024. 2. 8 | 本次共检验电力电缆15条， 15条所检项目合格 |  |
| 39 | GX-B1322/21-1-24045~24050 | 2024. 2. 8 | 本次共检验电力电缆6条，6 条所检项目合格 |  |
| 40 | GX-B1322/21-1-24051~24055 | 2024. 2. 8 | 本次共检验电力电缆5条，5 条所检项目合格 |  |

| | | | | |
|----|---------------------------|------------|----------------------------|--|
| 41 | GX-B1322/21-1-24056~24067 | 2024. 2. 8 | 本次共检验电力电缆12条, 12条所检项目合格 |  |
| 42 | GX-B1322/21-1-24068~24078 | 2024. 2. 8 | 本次共检验电力电缆11条, 11条所检项目合格 |  |
| 43 | GX-B1322/21-1-24079~24090 | 2024. 2. 8 | 本次共检验电力电缆12条, 12条所检项目合格 |  |

| | | | | |
|----|---------------------------|------------|---------------------------------------|--|
| 44 | GX-B1451/20-1-24089~24098 | 2024. 2. 7 | 本次共检继电保护装置 10台，10台继电保护装置所 检项目合格 |  |
| 45 | GX-B1451/20-1-24099~24116 | 2024. 2. 7 | 本次共检继电保护装置 18台，18台继电保护装置所 检项目合格 |  |
| 46 | GX-B1451/20-1-24117~24135 | 2024. 2. 7 | 本次共检继电保护装置 19台，19台继电保护装置所 检项目合格 |  |

| | | | | |
|----|---------------------------|------------|---------------------------------------|--|
| 47 | GX-B1451/20-1-24136~24149 | 2024. 2. 7 | 本次共检继电保护装置 14台，14台继电保护装置所 检项目合格 |  |
| 48 | GX-B1451/20-1-24150~24154 | 2024. 2. 7 | 本次共检继电保护装置5台， 5台继电保护装置所检项目合 格 |  |
| 49 | GX-B1451/20-1-24155~24163 | 2024. 2. 7 | 本次共检继电保护装置9台， 9台继电保护装置所检项目合 格 |  |

| | | | | |
|----|---------------------------|------------|---------------------------------------|--|
| 50 | GX-B1451/20-1-24164~24174 | 2024. 2. 7 | 本次共检继电保护装置 11台，11台继电保护装置所 检项目合格 |  |
| 51 | GX-B1451/20-1-24175~24190 | 2024. 2. 7 | 本次共检继电保护装置 16台，16台继电保护装置所 检项目合格 |  |
| 52 | GX-B1451/20-1-24191~24200 | 2024. 2. 7 | 本次共检继电保护装置 10台，10台继电保护装置所 检项目合格 |  |

| | | | | |
|----|---------------------------|------------|---------------------------------------|--|
| 53 | GX-B1451/20-1-24201~24215 | 2024. 2. 7 | 本次共检继电保护装置 15台，15台继电保护装置所 检项目合格 |  |
| 54 | GX-B1451/20-1-24216~24225 | 2024. 2. 7 | 本次共检继电保护装置 10台，10台继电保护装置所 检项目合格 |  |
| 55 | GX-B1451/20-1-24226~24227 | 2024. 2. 7 | 本次共检继电保护装置2台， 2台继电保护装置所检项目合 格 |  |

| | | | | |
|----|---------------------|-------------|--------|--|
| 56 | GX-B1534/20-1-24005 | 2024. 2. 22 | 所检项目合格 |  |
| 57 | GX-B1534/20-1-24006 | 2024. 2. 22 | 所检项目合格 |  |
| 58 | GX-B1534/20-1-24007 | 2024. 2. 22 | 所检项目合格 |  |

| | | | | |
|----|---------------------|-------------|---------------------------------|--|
| 59 | GX-B1534/20-1-24008 | 2024. 2. 22 | 所检项目合格 |  |
| 60 | GX-B1534/20-1-24009 | 2024. 2. 22 | 所检项目合格 |  |
| 61 | GX-B1424/20-1-24003 | 2024. 2. 20 | 依据NB/T 10176-2019单轨吊 车综合判定合格 |  |

| | | | | |
|----|---------------------|-------------|---------|--|
| 62 | GX-B1380/20-1-24001 | 2024. 2. 20 | 所检项目合格 |  |
| 63 | GX-B1517/20-1-24009 | 2024/2/23 | 综合判定：合格 |  |
| 64 | GX-B1517/20-1-24010 | 2024/2/23 | 综合判定：合格 |  |

| | | | | |
|----|---------------------|-----------|---------|---|
| 65 | GX-B1517/20-1-24011 | 2024/2/23 | 综合判定：合格 |  A photograph showing two workers in a tunnel. They are wearing red hard hats and blue work clothes. One worker is holding a flashlight. They are standing next to a red vehicle, possibly a small truck or bus, with the number '7' visible on its side. The tunnel walls are concrete and there are pipes and cables visible. A yellow timestamp '2024/1/30' is in the bottom right corner of the photo. |
|----|---------------------|-----------|---------|---|