




序号	报告编号	发布日期	结论	影像资料
1	GX-B1601/22-B-240053~240056	2024年3月1日	所检项目合格	 A photograph showing three technicians in grey uniforms working on a large, blue, curved piece of industrial equipment. One technician is leaning over the machine, another is standing nearby, and a third is in the foreground. A yellow timestamp '2024.2.18' is visible in the bottom right corner of the image.
2	GX-B1595/22-B-240016~240025	2024年3月1日	所检项目合格	 A photograph showing two technicians in grey uniforms working on a piece of industrial equipment with a control panel. One technician is adjusting a dial on the panel, while the other is holding a tool. A yellow timestamp '2024.1.30' is visible in the bottom right corner of the image.
3	GX-B1595/22-B-240026~240035	2024年3月1日	所检项目合格	 A photograph showing two technicians in grey uniforms working on a piece of industrial equipment. One technician is holding a green component, while the other is looking at it. A yellow timestamp '2024.1.31' is visible in the bottom right corner of the image.

4	GX-B1595/22-B-240036~240045	2024年3月1日	所检项目合格	 <p>2024.2.1</p>
5	GX-B1568/22-B-240033~240036	2024年3月1日	所检项目合格	 <p>2024.2.20</p>
6	GX-B1372/22-B-240122~240124	2024.3.1	所检项目合格	 <p>2024.2.3</p>

7	GX-B1372/22-B-240119~240121	2024.3.1	所检项目合格	
8	GX-B1540/20-B-240150~240158	2024.3.1	所检项目合格	
9	GX-B1540/20-B-240230~240249	2024.3.4	所检项目合格	

10	GX-B1542/21-B-24063~24074	2024.3.6	所检项目合格	
11	GX-B1531/20-B-240605~240617	2024.3.8	所检项目合格	
12	GX-B1531/20-B-240618~240624	2024.3.8	不合格	

13	GX-B1531/20-B-240641~240643	2024.3.8	不合格	
----	-----------------------------	----------	-----	---