

序号	报告编号	发布日期	结论	影像资料
75	GX-B1362/20-A-24066	2024/3/8	所检项目合格	 A photograph showing two male workers in grey work uniforms and gloves operating a large industrial machine in a workshop. The worker on the right is in the foreground, looking down at a component on a workbench. The worker on the left is slightly behind, also focused on the task. The machine is light-colored with a dark base. A yellow timestamp '2024/3/2' is visible in the bottom right corner of the image.
76	GX-B1362/20-A-24067	2024/3/8	所检项目合格	 A photograph showing two male workers in grey work uniforms and gloves operating a large industrial machine in a workshop. The worker on the right is in the foreground, looking down at a component on a workbench. The worker on the left is slightly behind, also focused on the task. The machine is light-colored with a dark base. A yellow timestamp '2024/3/2' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
77	GX-B1362/20-A-24068	2024/3/8	所检项目合格	
78	GX-B1362/20-A-24069	2024/3/8	所检项目合格	

序号	报告编号	发布日期	结论	影像资料	
79	GX-B1362/20-A-24070	2024/3/8	所检项目合格		
80	GX-B1361/22-A-24254	2024/3/14	所检项目合格		

序号	报告编号	发布日期	结论	影像资料
81	GX-B1361/22-A-24255	2024/3/14	所检项目合格	
82	GX-B1361/22-A-24256	2024/3/14	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
83	GX-B1361/22-A-24257	2024/3/14	所检项目合格	
84	GX-B1361/22-A-24258	2024/3/14	合格	

序号	报告编号	发布日期	结论	影像资料
85	GX-B1361/22-A-24259	2024/3/14	合格	
86	GX-B1361/22-A-24260	2024/3/14	合格	

序号	报告编号	发布日期	结论	影像资料	
87	GX-B1361/22-A-24261	2024/3/14	合格		
88	GX-B1361/22-A-24267	2024/3/14	所检项目合格		

序号	报告编号	发布日期	结论	影像资料
89	GX-B1361/22-A-24268	2024/3/14	不合格	 A photograph showing two men in grey work uniforms working at a large industrial machine. One man is leaning over the machine, and the other is standing next to him, looking at a component. A yellow timestamp '2024/3/9' is visible in the bottom right corner of the image.
90	GX-B1361/22-A-24269	2024/3/14	所检项目合格	 A photograph showing two men in grey work uniforms working at a large industrial machine. One man is leaning over the machine, and the other is standing next to him, looking at a component. A yellow timestamp '2024/3/9' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
91	GX-B1361/22-A-24270	2024/3/14	所检项目合格	
92	GX-B1361/22-A-24271	2024/3/14	合格	

序号	报告编号	发布日期	结论	影像资料
93	GX-B1361/22-A-24272	2024/3/14	所检项目合格	 A photograph showing two workers in a workshop. One worker is operating a large industrial machine, and the other is handling materials. The date stamp '2024/3/10' is visible in the bottom right corner.
94	GX-B1361/22-A-24273	2024/3/14	不合格	 A photograph showing a worker in a workshop operating a machine. The date stamp '2024/3/10' is visible in the bottom right corner.

序号	报告编号	发布日期	结论	影像资料
95	GX-B1361/22-A-24274	2024/3/14	合格	
96	GX-B1361/22-A-24275	2024/3/14	合格	

序号	报告编号	发布日期	结论	影像资料
97	GX-B1361/22-A-24232	2024/3/14	所检项目合格	
98	GX-B1361/22-A-24233	2024/3/14	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
99	GX-B1361/22-A-24234	2024/3/14	所检项目合格	
100	GX-B1361/22-A-24235	2024/3/14	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
101	GX-B1361/22-A-24236	2024/3/14	所检项目合格	 A photograph showing two male workers in grey work jackets in a factory. The worker on the right is in the foreground, wearing yellow gloves and working on a component. The worker on the left is in the background, operating a large industrial machine. A yellow timestamp '2024/3/1' is visible in the bottom right corner of the image.
102	GX-B1361/22-A-24237	2024/3/14	不合格	 A photograph showing two male workers in grey work jackets in a factory. The worker on the right is in the foreground, looking down at a component on a workbench. The worker on the left is in the background, operating a large industrial machine. A yellow timestamp '2024/3/1' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
103	GX-B1361/22-A-24238	2024/3/14	所检项目合格	
104	GX-B1361/22-A-24239	2024/3/14	不合格	

序号	报告编号	发布日期	结论	影像资料
105	GX-B1361/22-A-24240	2024/3/14	不合格	
106	GX-B1361/22-A-24241	2024/3/14	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
107	GX-B1361/22-A-24242	2024/3/14	所检项目合格	
108	GX-B1361/22-A-24243	2024/3/14	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
109	GX-B1361/22-A-24244	2024/3/14	所检项目合格	
110	GX-B1361/22-A-24249	2024/3/14	不合格	

序号	报告编号	发布日期	结论	影像资料
111	GX-B1361/22-A-24280	2024/3/14	所检项目合格	
112	GX-B1361/22-A-24247	2024/3/14	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
113	GX-B1361/22-A-24248	2024/3/14	所检项目合格	
114	GX-B1362/20-A-24077	2024/3/14	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
115	GX-B1362/20-A-24078	2024/3/14	所检项目合格	 A photograph showing two male workers in grey work uniforms in a factory. One worker is operating a large industrial machine on the left, while the other stands to the right, handling a large metal tray filled with small, perforated components. A yellow timestamp '2024/3/7' is visible in the bottom right corner of the image.
116	GX-B1362/20-A-24079	2024/3/14	所检项目合格	 A photograph showing a male worker in a grey work uniform in a factory. He is wearing gloves and is focused on a task at a workbench. In the background, another worker is visible at a different machine. A yellow timestamp '2024/3/7' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
117	GX-B1362/20-A-24080	2024/3/14	所检项目合格	
118	GX-B1362/20-A-24081	2024/3/14	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
119	GX-B1362/20-A-24082	2024/3/14	所检项目合格	
120	GX-B1362/20-A-24083	2024/3/14	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
121	GX-B1362/20-A-24084	2024/3/14	所检项目合格	
122	GX-B1362/20-A-24085	2024/3/14	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
123	GX-B1362/20-A-24086	2024/3/14	所检项目合格	