

序号	报告编号	发布日期	结论	影像资料
27	GX-B1363/22-A-24129	2024/4/2	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
28	GX-B1363/22-A-24128	2024/4/2	所检项目合格。	 A photograph showing two workers in white uniforms and gloves inspecting a large, complex industrial machine. The machine has a large, dark, rectangular opening. The workers are positioned on either side of the opening, looking into it. The background shows a white wall and a window. A green trash bin is visible on the left. A timestamp '2024/03/21' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
29	GX-B1363/22-A-24130	2024/4/2	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
30	GX-B1363/22-A-24140	2024/4/2	粘合强度不合格，其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
31	GX-B1363/22-A-24139	2024/4/2	粘合强度不合格，其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
32	GX-B1363/22-A-24147	2024/4/2	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
33	GX-B1363/22-A-24146	2024/4/2	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
34	GX-B1363/22-A-24145	2024/4/2	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
35	GX-B1363/22-A-24138	2024/4/2	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
36	GX-B1538/22-A-24023	2024/3/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
37	GX-B1363/22-A-24173	2024/4/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
38	GX-B1364/22-A-24340	2024/4/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
39	GX-B1363/22-A-24141	2024/4/3	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
40	GX-B1364/22-A-24409	2024/4/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
41	GX-B1364/22-A-24419	2024/4/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
42	GX-B1457/22-A-24001	2024/4/10	共检验矿用圆环链用开口式连接环1件,所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
43	GX-B1363/22-A-24162	2024/4/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
44	GX-B1363/22-A-24164	2024/4/9	所检项目合格。	