

序号	报告编号	发布日期	结论	影像资料	
45	GX-B1362/20-A-24098	2024/4/7	最小钢丝破断拉力总和 3076.22 ，其余所检项目合格		
46	GX-B1362/20-A-24099	2024/4/7	最小钢丝破断拉力总和 3054.11 ，其余所检项目合格		

序号	报告编号	发布日期	结论	影像资料	
47	GX-B1362/20-A-24100	2024/4/7	最小钢丝破断拉力总和 3055.02 ，其余所检项目合格		
48	GX-B1362/20-A-24101	2024/4/7	最小钢丝破断拉力总和 3088.55 ，其余所检项目合格		

序号	报告编号	发布日期	结论	影像资料	
49	GX-B1362/20-A-24102	2024/4/7	最小钢丝破断拉力总和 3061.83 ，其余所检项目合格		
50	GX-B1362/20-A-24103	2024/4/7	最小钢丝破断拉力总和 3067.58 ，其余所检项目合格		

序号	报告编号	发布日期	结论	影像资料
51	GX-B1362/20-A-24104	2024/4/7	合格	
52	GX-B1362/20-A-24105	2024/4/7	不合格	

序号	报告编号	发布日期	结论	影像资料
53	GX-B1362/20-A-24106	2024/4/7	不合格	
54	GX-B1362/20-A-24107	2024/4/7	合格	

序号	报告编号	发布日期	结论	影像资料	
55	GX-B1362/20-A-24108	2024/4/7	合格		
56	GX-B1361/22-A-24328	2024/4/7	所检项目合格		

序号	报告编号	发布日期	结论	影像资料	
57	GX-B1361/22-A-24329	2024/4/7	所检项目合格		
58	GX-B1361/22-A-24330	2024/4/7	所检项目合格		

序号	报告编号	发布日期	结论	影像资料
59	GX-B1361/22-A-24331	2024/4/7	所检项目合格	
60	GX-B1361/22-A-24332	2024/4/7	所检项目合格	

序号	报告编号	发布日期	结论	影像资料	
61	GX-B1361/22-A-24333	2024/4/7	所检项目合格		
62	GX-B1361/22-A-24334	2024/4/7	所检项目合格		

序号	报告编号	发布日期	结论	影像资料	
63	GX-B1361/22-A-24335	2024/4/7	所检项目合格		
64	GX-B1361/22-A-24336	2024/4/7	所检项目合格		

序号	报告编号	发布日期	结论	影像资料
65	GX-B1361/22-A-24345	2024/4/7	合格	
66	GX-B1361/22-A-24346	2024/4/7	合格	

序号	报告编号	发布日期	结论	影像资料
67	GX-B1361/22-A-24347	2024/4/7	合格	
68	GX-B1361/22-A-24348	2024/4/8	所检项目合格	

序号	报告编号	发布日期	结论	影像资料	
69	GX-B1361/22-A-24349	2024/4/8	所检项目合格		
70	GX-B1361/22-A-24350	2024/4/8	所检项目合格		

序号	报告编号	发布日期	结论	影像资料	
71	GX-B1361/22-A-24351	2024/4/8	所检项目合格		
72	GX-B1361/22-A-24352	2024/4/8	所检项目合格		

序号	报告编号	发布日期	结论	影像资料
73	GX-B1361/22-A-24353	2024/4/8	所检项目合格	
74	GX-B1361/22-A-24354	2024/4/8	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
75	GX-B1361/22-A-24355	2024/4/8	所检项目合格	 A photograph showing two male workers in a workshop. They are wearing light-colored work jackets and yellow gloves. They are standing at a large industrial machine, possibly a lathe or mill, and appear to be working on a component. The date '2024/3/31' is visible in the bottom right corner of the image.
76	GX-B1361/22-A-24356	2024/4/8	所检项目合格	 A photograph showing a worker in a workshop. The worker is wearing a light-colored work jacket and yellow gloves, and is focused on a task at a workbench. In the background, another worker is visible near a large machine. The date '2024/3/31' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料	
77	GX-B1361/22-A-24357	2024/4/8	所检项目合格		
78	GX-B1361/22-A-24364	2024/4/8	所检项目合格		

序号	报告编号	发布日期	结论	影像资料
79	GX-B1361/22-A-24365	2024/4/8	所检项目合格	
80	GX-B1361/22-A-24366	2024/4/8	合格	

序号	报告编号	发布日期	结论	影像资料	
81	GX-B1361/22-A-24367	2024/4/8	合格		
82	GX-B1361/22-A-24368	2024/4/8	所检项目合格		

序号	报告编号	发布日期	结论	影像资料
83	GX-B1361/22-A-24369	2024/4/8	所检项目合格	 A photograph showing a worker in a grey uniform operating a machine in a workshop. The worker is focused on the task, and the machine is a large, industrial-grade piece of equipment. The background shows a typical workshop environment with various tools and equipment. A yellow timestamp '2024/4/5' is visible in the bottom right corner of the image.
84	GX-B1361/22-A-24370	2024/4/8	所检项目合格	 A photograph showing two workers in grey uniforms operating a machine in a workshop. The workers are focused on their tasks, and the machine is a large, industrial-grade piece of equipment. The background shows a typical workshop environment with various tools and equipment. A yellow timestamp '2024/4/5' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
85	GX-B1361/22-A-24371	2024/4/8	所检项目合格	
86	GX-B1361/22-A-24372	2024/4/8	所检项目合格	

序号	报告编号	发布日期	结论	影像资料	
87	GX-B1362/20-A-24110	2024/4/8	所检项目合格		
88	GX-B1362/20-A-24111	2024/4/8	不合格		

序号	报告编号	发布日期	结论	影像资料	
89	GX-B1362/20-A-24122	2024/4/8	合格		
90	GX-B1362/20-A-24112	2024/4/15	所检项目合格		

序号	报告编号	发布日期	结论	影像资料
91	GX-B1362/20-A-24113	2024/4/15	所检项目合格	 A photograph showing two male workers in grey work uniforms and white gloves operating a large industrial machine in a workshop. The worker on the right is in the foreground, focused on his task. The worker on the left is slightly behind him. A yellow timestamp '2024/4/3' is visible in the bottom right corner of the image.
92	GX-B1362/20-A-24114	2024/4/15	所检项目合格	 A photograph showing two male workers in grey work uniforms and white gloves operating a large industrial machine in a workshop. The worker on the right is in the foreground, focused on his task. The worker on the left is slightly behind him. A yellow timestamp '2024/4/3' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料	
93	GX-B1362/20-A-24115	2024/4/15	所检项目合格		
94	GX-B1362/20-A-24116	2024/4/15	所检项目合格		

序号	报告编号	发布日期	结论	影像资料
95	GX-B1362/20-A-24117	2024/4/15	所检项目合格	
96	GX-B1362/20-A-24118	2024/4/15	所检项目合格	

序号	报告编号	发布日期	结论	影像资料	
97	GX-B1362/20-A-24119	2024/4/15	所检项目合格		
98	GX-B1362/20-A-24120	2024/4/15	所检项目合格		

序号	报告编号	发布日期	结论	影像资料	
99	GX-B1362/20-A-24121	2024/4/15	所检项目合格		
100	GX-B1361/22-A-24373	2024/4/15	所检项目合格		

序号	报告编号	发布日期	结论	影像资料
101	GX-B1361/22-A-24374	2024/4/15	所检项目合格	
102	GX-B1361/22-A-24375	2024/4/15	所检项目合格	

序号	报告编号	发布日期	结论	影像资料	
103	GX-B1361/22-A-24376	2024/4/15	所检项目合格		
104	GX-B1361/22-A-24377	2024/4/15	所检项目合格		

序号	报告编号	发布日期	结论	影像资料	
105	GX-B1361/22-A-24378	2024/4/15	所检项目合格		
106	GX-B1361/22-A-24379	2024/4/15	所检项目合格		

序号	报告编号	发布日期	结论	影像资料
107	GX-B1361/22-A-24380	2024/4/15	所检项目合格	
108	GX-B1361/22-A-24381	2024/4/15	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
109	GX-B1361/22-A-24382	2024/4/15	所检项目合格	
110	GX-B1361/22-A-24383	2024/4/15	所检项目合格	

序号	报告编号	发布日期	结论	影像资料	
111	GX-B1361/22-A-24384	2024/4/15	所检项目合格		
112	GX-B1361/22-A-24385	2024/4/15	所检项目合格		

序号	报告编号	发布日期	结论	影像资料	
113	GX-B1361/22-A-24386	2024/4/15	所检项目合格		
114	GX-B1361/22-A-24387	2024/4/15	所检项目合格		

序号	报告编号	发布日期	结论	影像资料	
115	GX-B1361/22-A-24388	2024/4/15	所检项目合格		
116	GX-B1362/20-A-24137	2024/4/17	合格		

序号	报告编号	发布日期	结论	影像资料
117	GX-B1362/20-A-24138	2024/4/17	合格	