

序号	报告编号	发布日期	结论	影像资料
246	GX-B1521/20-Y-24382	2024年6月6日	所检项目合格。	 A photograph showing a worker in a white uniform and red helmet operating a piece of machinery, possibly a generator or engine, in an industrial setting. The worker is holding a small object, possibly a tool or a component. The date stamp '2024/5/28' is visible in the bottom right corner of the image.
247	GX-B1521/20-Y-24383	2024年6月6日	所检项目合格。	 A photograph of a yellow excavator in a desert environment. The excavator is positioned on a sandy surface, and its bucket is raised. Two workers in safety gear are standing near the base of the excavator. The date stamp '2024/5/28' is visible in the bottom right corner of the image.

248	GX-B1521/20-Y-24384	2024年6月6日	所检项目合格。	
249	GX-B1521/20-Y-24385	2024年6月6日	所检项目合格。	

250	GX-B1521/20-Y-24386	2024年6月6日	所检项目合格。	 A yellow Komatsu excavator is shown in profile, facing right, at a construction site. The excavator's arm is raised, and its bucket is open. Two workers in blue and white uniforms are standing near the base of the machine. The background shows a dirt embankment under a clear blue sky. A yellow timestamp '2024/6/28' is visible in the bottom right corner of the photo.
251	GX-B1521/20-Y-24387	2024年6月6日	所检项目合格。	 A yellow Komatsu excavator is shown from a low angle, facing left, at a construction site. The excavator's arm is raised, and its bucket is open. Two workers in blue and white uniforms are standing near the base of the machine. The background shows a dirt embankment under a clear blue sky. A yellow timestamp '2024/6/28' is visible in the bottom right corner of the photo.

252	GX-B1521/20-Y-24388	2024年6月6日	所检项目合格。	
253	GX-B1539/22-Y-24204	2024年6月6日	所检项目合格。	

254	GX-B1539/22-Y-24205	2024年6月6日	所检项目合格。	
255	GX-B1539/22-Y-24206	2024年6月6日	所检项目合格。	

256	GX-B1539/22-Y-24207	2024年6月6日	所检项目合格。	
257	GX-B1539/22-Y-24208	2024年6月6日	所检项目合格。	

258	GX-B1321/20-Y-24195~24206	2024年6月6日	本次共检验电力电缆12条，12条电力电缆所检项目合格。	
259	GX-B1321/20-Y-24248	2024年6月6日	所检项目合格。	

260	GX-B1321/20-Y-24255~24267	2024年6月6日	本次共检验电力电缆13条，13条电力电缆所检项目合格。	
261	GX-B1321/20-Y-24268~24278	2024年6月6日	本次共检验电力电缆11条，11条电力电缆所检项目合格。	



262	GX-B1321/20-Y-24279~24290	2024年6月6日	本次共检验电力电缆12条，12条电力电缆所检项目合格。	
263	GX-B1321/20-Y-24291~24298	2024年6月6日	本次共检验电力电缆8条，8条电力电缆所检项目合格。	

264	GX-B1321/20-Y-24299~24301	2024年6月6日	本次共检验电力电缆3条，3条电力电缆所检项目合格。	 A photograph showing a worker in a red hard hat and safety gear testing a cable inside a cabinet. The worker is holding a red tool, and a digital display on the floor shows a reading. The date stamp in the bottom right corner of the photo is 2024/4/12.
265	GX-B1321/20-Y-24302~24311	2024年6月6日	本次共检验电力电缆10条，10条电力电缆所检项目合格。	 A photograph showing a worker in a black hard hat and safety gear testing a cable inside a cabinet. The worker is kneeling and holding a red tool, and a digital display on the floor shows a reading. The date stamp in the bottom right corner of the photo is 2024/4/8.

266	GX-B1321/20-Y-24312~24323	2024年6月6日	本次共检验电力电缆12条，12条电力电缆所检项目合格。	
267	GX-B1321/20-Y-24182~24194	2024年6月6日	本次共检验电力电缆13条，13条电力电缆所检项目合格。	

268	GX-B1521/20-Y-24427	2024. 6. 7	所检项目合格。	
269	GX-B1521/20-Y-24428	2024. 6. 7	所检项目合格。	

270	GX-B1521/20-Y-24429	2024. 6. 7	所检项目合格。	
271	GX-B1308/23-Y-24001	2024. 6. 7	综合判定：合格。	

272	GX-B1557/22-Y-24032	2024年6月7日	所检项目合格。	
273	GX-B1557/22-Y-24030	2024年6月7日	所检项目合格。	

274	GX-B1557/22-Y-24031	2024年6月7日	所检项目合格。	
275	GX-B1563/24-Y-24035	2024年6月7日	所检项目合格。	



276	GX-B1539/22-Y-24226	2024年6月7日	所检项目合格。	
277	GX-B1539/22-Y-24227	2024年6月7日	所检项目合格。	



278	GX-B1521/20-Y-24430	2024年6月7日	所检项目合格。	
279	GX-B1521/20-Y-24431	2024年6月7日	所检项目合格。	

280	GX-B1521/20-Y-24432	2024年6月7日	所检项目合格。	 A worker wearing a red hard hat and a white uniform is seated in the operator's seat of a piece of machinery, possibly a forklift or a small tractor. The worker is holding a control device. The background shows the interior of the machine with various controls and a "ZOOML" logo. A yellow timestamp "2024/6/30" is visible in the bottom right corner of the photo.
281	GX-B1521/20-Y-24433	2024年6月7日	所检项目合格。	 A worker wearing a red hard hat and a white uniform is sitting in the driver's seat of a vehicle, possibly a truck or a large forklift. The worker is holding a device. The view is from outside the vehicle looking into the cab. A yellow timestamp "2024/5/30" is visible in the bottom right corner of the photo.

282	GX-B1522/20-Y-24088	2024年6月11日	所检项目合格。	
283	GX-B1522/20-Y-24089	2024年6月11日	所检项目合格。	

284	GX-B1522/20-Y-24090	2024年6月11日	所检项目合格。	
285	GX-B1522/20-Y-24091	2024年6月11日	所检项目合格。	

286	GX-B1522/20-Y-24092	2024年6月11日	所检项目合格。	
287	GX-B1522/20-Y-24093	2024年6月11日	所检项目合格。	

288	GX-B1321/20-Y-24339	2024年6月7日	所检项目合格。	
289	GX-B1321/20-Y-24340~24343	2024年6月7日	本次共检电力电缆4条， 4条电力电缆所检项目合格。	

290	GX-B1321/20-Y-24344~24347	2024年6月7日	本次共检电力电缆4条， 4条电力电缆所检项目合格。	
291	GX-B1321/20-Y-24348	2024年6月7日	所检项目合格。	



292	GX-B1321/20-Y-24349	2024年6月7日	所检项目合格。	
293	GX-B1321/20-Y-24350~24352	2024年6月7日	本次共检电力电缆3条， 3条电力电缆所检项目合格。	



294	GX-B1321/20-Y-24353~24355	2024年6月7日	本次共检电力电缆3条， 3条电力电缆所检项目合格。	
295	GX-B1321/20-Y-24356	2024年6月7日	所检项目合格。	

296	GX-B1499/23-Y-24033	2024年6月12日	实测流量为182.1m <sup>3</sup> /h。	
297	GX-B1499/23-Y-24034	2024年6月12日	实测流量为177.5m <sup>3</sup> /h。	

298	GX-B1559/22-Y-24017	2024年6月12日	所检项目合格。	
299	GX-B1557/22-Y-24033	2024年6月12日	所检项目合格。	

300	GX-B1557/22-Y-24034	2024年6月12日	所检项目合格。	
301	GX-B1557/22-Y-24035	2024年6月12日	所检项目合格。	

302	GX-B1557/22-Y-24036	2024年6月12日	所检项目合格。	
303	GX-B1557/22-Y-24037	2024年6月12日	所检项目合格。	

304	GX-B1557/22-Y-24038	2024年6月12日	所检项目合格。	
305	GX-B1563/24-Y-24036	2024年6月12日	所检项目合格。	

306	GX-B1563/24-Y-24037	2024年6月12日	所检项目合格。	 A yellow tanker truck with 'MS40' and 'HF2103' markings is parked on a dirt surface. Two workers in safety gear stand in front of it. A yellow date stamp '2024/6/5' is visible in the bottom right corner of the photo.
307	GX-B1563/24-Y-24038	2024年6月12日	所检项目合格。	 A yellow tanker truck with 'MS40' and 'HF2104' markings is parked on a dirt surface. Two workers in safety gear stand in front of it. A yellow date stamp '2024/6/5' is visible in the bottom right corner of the photo.

308	GX-B1563/24-Y-24039	2024年6月12日	所检项目合格。	
309	GX-B1563/24-Y-24040	2024年6月12日	所检项目合格。	



310	GX-B1563/24-Y-24041	2024年6月12日	所检项目合格。	
311	GX-B1563/24-Y-24042	2024年6月12日	所检项目合格。	

312	GX-B1556/22-Y-24016	2024年6月12日	所检项目合格。	 A photograph of a yellow tracked loader with the identification number 'MF1032' on its front. Two workers wearing red hard hats and safety gear are standing in front of the machine. The date '2024/6/4' is visible in the bottom right corner of the photo.
313	GX-B1556/22-Y-24017	2024年6月12日	所检项目合格。	 A photograph of a yellow tracked loader with the identification number 'MF1033' on its front. Two workers wearing safety gear are standing in front of the machine. The date '2024/6/4' is visible in the bottom right corner of the photo.

314	GX-B1521/20-Y-24442	2024年6月12日	所检项目合格。	 A worker wearing a white long-sleeved uniform and a pink hard hat is inspecting a large, yellow, cylindrical component inside a machine. The worker is holding a tool and looking at the component. A yellow timestamp "2024/6/2" is visible in the bottom right corner of the image.
315	GX-B1521/20-Y-24443	2024年6月12日	所检项目合格。	 A yellow XCMG tracked excavator is parked on a dirt surface at a construction site. A worker in a white uniform and pink hard hat is standing next to the excavator. The excavator has "XCMG" written on its arm. A yellow timestamp "2024/6/2" is visible in the bottom right corner of the image.

316	GX-B1521/20-Y-24444	2024年6月12日	所检项目合格。	
317	GX-B1521/20-Y-24445	2024年6月12日	所检项目合格。	

318	GX-B1521/20-Y-24446	2024年6月12日	所检项目合格。	
319	GX-B1539/22-Y-24228	2024年6月12日	所检项目合格。	

320	GX-B1539/22-Y-24229	2024年6月12日	所检项目合格。	
321	GX-B1539/22-Y-24230	2024年6月12日	所检项目合格。	

322	GX-B1321/20-Y-24404~24407	2024年6月12日	本次共检验电力电缆4条，4条电力电缆所检项目合格。	
323	GX-B1321/20-Y-24408	2024年6月12日	所检项目合格。	

324	GX-B1522/20-Y-24073	2024年6月12日	所检项目合格。	
325	GX-B1522/20-Y-24074	2024年6月12日	所检项目合格。	



326	GX-B1522/20-Y-24075	2024年6月12日	所检项目合格。	
327	GX-B1522/20-Y-24076	2024年6月12日	所检项目合格。	



328	GX-B1310/21-Y-24114	2024. 6. 12	符合标准要求。	
329	GX-B1427/21-Y-24114	2024. 6. 12	无缺陷磁痕显示。	

330	GX-B1515/22-Y-24007	2024年6月13日	所检项目合格。	
331	GX-B1515/22-Y-24008	2024年6月13日	所检项目合格。	

332	GX-B1521/20-Y-24447	2024年6月12日	所检项目合格	
333	GX-B1310/21-Y-24108	2024年6月13日	符合标准要求。	

334	GX-B1310/21-Y-24107	2024年6月13日	符合标准要求。	 <p>2024/5/12</p>
335	GX-B1310/21-Y-24106	2024年6月13日	符合标准要求。	 <p>2024/5/12</p>

336	GX-B1310/21-Y-24110	2024年6月13日	符合标准要求。	
337	GX-B1428/21-Y-24110	2024年6月13日	无缺陷迹痕显示。	



338	GX-B1310/21-Y-24111	2024年6月13日	符合标准要求。	
339	GX-B1428/21-Y-24111	2024年6月13日	无缺陷迹痕显示。	

340	GX-B1310/21-Y-24112	2024年6月13日	符合标准要求。	
341	GX-B1428/21-Y-24112	2024年6月13日	无缺陷迹痕显示。	





342	GX-B1310/21-Y-24113	2024年6月13日	符合标准要求。	
343	GX-B1428/21-Y-24113	2024年6月13日	无缺陷迹痕显示。	



344	GX-B1310/21-Y-24108	2024年6月13日	符合标准要求。	
345	GX-B1328/20-Y-24040	2023年6月13日	本次共检验电器10支， 10支验电器所检项目合格。	

346	GX-B1328/20-Y-24041	2023年6月13日	本次共检接地装置9组，9组接地装置所检项目合格。	
347	GX-B1321/20-Y-24358~24361	2023年6月13日	本次共检验电力电缆4条，4条电力电缆所检项目合格。	

348	GX-B1321/20-Y-24362~24367	2023年6月13日	本次共检验电力电缆6条，6条电力电缆所检项目合格。	 <p>2024/5/12</p>
349	GX-B1321/20-Y-24368~24372	2023年6月13日	本次共检验电力电缆5条，5条电力电缆所检项目合格。	 <p>2024/5/13</p>

350	GX-B1321/20-Y-24373~24381	2023年6月13日	本次共检验电力电缆 9条，9条电力电缆所检 项目合格。	
351	GX-B1321/20-Y-24382~24384	2023年6月13日	本次共检验电力电缆 3条，3条电力电缆所检 项目合格。	

352	GX-B1321/20-Y-24385~24388	2023年6月13日	本次共检验电力电缆4条，4条电力电缆所检项目合格。	 <p>2024/5/19</p>
353	GX-B1321/20-Y-24389~24400	2023年6月13日	本次共检验电力电缆12条，12条电力电缆所检项目合格。	 <p>2024/5/20</p>

354	GX-B1321/20-Y-24401~24402	2023年6月13日	本次共检验电力电缆 2条，2条电力电缆所检 项目合格。	
355	GX-B1321/20-Y-24403	2023年6月13日	所检项目合格。	



356	GX-B1522/20-Y-24077	2024年6月13日	所检项目合格。	 A photograph of a large industrial drilling rig in a desert environment. The rig is orange and black, with a tall vertical mast. Two workers in blue and white uniforms are standing near the rig. The date stamp '2024/5/24' is visible in the bottom right corner.
357	GX-B1522/20-Y-24078	2024年6月13日	所检项目合格。	 A photograph of a worker wearing a red helmet and a white uniform, sitting in the operator's seat of a machine. The worker is holding a clipboard and looking at a control panel with various buttons and screens. The date stamp '2024/5/24' is visible in the bottom left corner.



358	GX-B1522/20-Y-24079	2024年6月13日	所检项目合格。	
359	GX-B1522/20-Y-24080	2024年6月13日	所检项目合格。	

360	GX-B1522/20-Y-24081	2024年6月13日	所检项目合格。	
361	GX-B1522/20-Y-24082	2024年6月13日	所检项目合格。	

362	GX-B1522/20-Y-24083	2024年6月13日	所检项目合格。	
363	GX-B1522/20-Y-24084	2024年6月13日	所检项目合格。	

364	GX-B1522/20-Y-24085	2024年6月13日	所检项目合格。	
365	GX-B1522/20-Y-24086	2024年6月13日	所检项目合格。	

366	GX-B1522/20-Y-24087	2024年6月13日	所检项目合格。	
367	GX-B1321/20-Y-24229~24236	2024年6月13日	本次共检验电力电缆8条，8条电力电缆所检项目合格。	

368	GX-B1321/20-Y-24240~24245	2024年6月13日	本次共检验电力电缆6条，6条电力电缆所检项目合格。	
369	GX-B1321/20-Y-24250~24253	2024年6月13日	本次共检验电力电缆4条，4条电力电缆所检项目合格。	

370	GX-B1321/20-Y-24409~24411	2024年6月13日	本次共检验电力电缆3条，3条电力电缆所检项目合格。	
371	GX-B1321/20-Y-24412~24414	2024年6月13日	本次共检验电力电缆3条，3条电力电缆所检项目合格。	

372	GX-B1321/20-Y-24415~24417	2024年6月13日	本次共检验电力电缆3条，3条电力电缆所检项目合格。	
373	GX-B1321/20-Y-24418~24420	2024年6月13日	本次共检验电力电缆3条，3条电力电缆所检项目合格。	



374	GX-B1321/20-Y-24421~24423	2024年6月13日	本次共检验电力电缆3条，3条电力电缆所检项目合格。	
375	GX-B1321/20-Y-24424~24426	2024年6月13日	本次共检验电力电缆3条，3条电力电缆所检项目合格。	