

序号	报告编号	发布日期	结论	影像资料
68	GX-B1305/21-1-24011	2024. 7. 15	综合判定：合格	
69	GX-B1328/20-1-24039	2024. 7. 17	本次共检绝缘胶垫10个，10个绝缘胶垫合格	


70	GX-B1321/20-1-24796~24802	2024. 7. 17	本次共检电力电缆7条，7条电力电缆所检项目合格	
71	GX-B1321/20-1-24791~24795	2024. 7. 17	本次共检电力电缆5条，5条电力电缆所检项目合格	

72	GX-B1305/21-1-24012	2024. 7. 18	综合判定：合格	
73	GX-B1305/21-1-24013	2024. 7. 18	综合判定：合格	

74	GX-B1309/21-1-24018	2024. 7. 19	所检项目合格	 <p>A worker in a red safety suit and helmet stands in a tunnel, holding a device. Green pipes are visible in the background. A yellow timestamp '2024/6/18' is at the bottom right.</p>
75	GX-B1500/21-1-24082	2024. 7. 19	综合判定：合格	 <p>A worker in a red safety suit and helmet is working on a large green pipe. The worker is wearing a red helmet and a red safety suit with reflective stripes. A yellow timestamp '2024/6/18' is at the bottom right.</p>

76	GX-B1500/21-1-24083	2024. 7. 19	综合判定：合格	
77	GX-B1500/21-1-24084	2024. 7. 19	综合判定：合格	

78	GX-B1309/21-1-24019	2024. 7. 19	所检项目合格	
79	GX-B1500/21-1-24085	2024. 7. 19	综合判定：合格	

80	GX-B1500/21-1-24086	2024. 7. 19	综合判定：合格	 <p>2024/6/18</p>
81	GX-B1500/21-1-24087	2024. 7. 19	综合判定：合格	 <p>2024/6/18</p>