

序号	报告编号	发布日期	结论	影像资料
273	GX-B1598/24-2-24144	2024. 7. 19	实测钢丝绳有效截面积损失百分比最大为1.58%，小于5%为正常。	
274	GX-B1598/24-2-24145	2024. 7. 19	实测钢丝绳有效截面积损失百分比最大为1.73%，小于5%为正常。	

275	GX-B1598/24-2-24146	2024. 7. 19	实测钢丝绳有效截面积损失百分比最大为1.24%，小于5%为正常。	
276	GX-B1598/24-2-24147	2024. 7. 19	实测钢丝绳有效截面积损失百分比最大为1.65%，小于5%为正常。	
277	GX-B1598/24-2-24148	2024. 7. 19	实测钢丝绳有效截面积损失百分比最大为1.12%，小于5%为正常。	

278	GX-B1598/24-2-24149	2024. 7. 19	实测钢丝绳有效截面积损失百分比最大为1.86%，小于5%为正常。	 <p>2024/07/05</p>
279	GX-B1310/21-2-24227	2024. 7. 19	符合标准要求。	 <p>2024/07/05</p>
280	GX-B1427/21-2-24227	2024. 7. 19	符合标准要求。	 <p>2024/07/05</p>

281	GX-B1310/21-2-24228	2024. 7. 19	符合标准要求。	
282	GX-B1427/21-2-24228	2024. 7. 19	符合标准要求。	
283	GX-B1321/20-2-24378~24381	2024. 7. 22	本次共检验电力电缆4条, 4条所检项目合格。	

284	GX-B1321/20-2-24382~24385	2024. 7. 22	本次共检验电力电缆4条, 4条所检项目合格。	
285	GX-B1321/20-2-24386~24390	2024. 7. 22	本次共检验电力电缆5条, 5条所检项目合格。	
286	GX-B1321/20-2-24391~24394	2024. 7. 22	本次共检验电力电缆4条, 4条所检项目合格。	


287	GX-B1321/20-2-24395~24397	2024. 7. 22	本次共检验电力电缆3条, 3条所检项目合格。	
288	GX-B1321/20-2-24398~24401	2024. 7. 22	本次共检验电力电缆4条, 4条所检项目合格。	
289	GX-B1321/20-2-24402~24408	2024. 7. 22	本次共检验电力电缆7条, 7条所检项目合格。	

290	GX-B1321/20-2-24409~24412	2024. 7. 22	本次共检验电力电缆4条, 4条所检项目合格。	
291	GX-B1321/20-2-24413~24417	2024. 7. 22	本次共检验电力电缆5条, 5条所检项目合格。	
292	GX-B1321/20-2-24418~24419	2024. 7. 22	本次共检验电力电缆2条, 2条所检项目合格。	

293	GX-B1321/20-2-24420~24425	2024. 7. 22	本次共检验电力电缆6条, 6条所检项目合格。	
294	GX-B1321/20-2-24426~24429	2024. 7. 22	本次共检验电力电缆4条, 4条所检项目合格。	
295	GX-B1321/20-2-24430~24434	2024. 7. 22	本次共检验电力电缆5条, 5条所检项目合格。	

296	GX-B1321/20-2-24435~24439	2024. 7. 22	本次共检验电力电缆5条, 5条所检项目合格。	
297	GX-B1321/20-2-24440~24442	2024. 7. 22	本次共检验电力电缆3条, 3条所检项目合格。	
298	GX-B1321/20-2-24443~24445	2024. 7. 22	本次共检验电力电缆3条, 3条所检项目合格。	

299	GX-B1321/20-2-24446~24452	2024. 7. 22	本次共检验电力电缆7条, 7条所检项目合格。	
300	GX-B1321/20-2-24453~24458	2024. 7. 22	本次共检验电力电缆6条, 6条所检项目合格。	
301	GX-B1321/20-2-24459~24465	2024. 7. 22	本次共检验电力电缆7条, 7条所检项目合格。	

302	GX-B1310/21-2-24234	2024/7/22	符合标准要求	 <p>2024/07/08</p>
303	GX-B1310/21-2-24235	2024/7/22	符合标准要求	 <p>2024/07/08</p>
304	GX-B1310/21-2-24236	2024/7/22	符合标准要求	 <p>2024/07/09</p>

305	GX-B1310/21-2-24237	2024/7/22	符合标准要求	
306	GX-B1310/21-2-24229	2024/7/22	符合标准要求	
307	GX-B1427/21-2-24229	2024/7/22	符合标准要求	

308	GX-B1310/21-2-24230	2024/7/22	符合标准要求	 <p>2024/07/11</p>
309	GX-B1427/21-2-24230	2024/7/22	符合标准要求	 <p>2024/07/11</p>
310	GX-B1310/21-2-24231	2024/7/22	符合标准要求	 <p>2024/07/11</p>

311	GX-B1427/21-2-24231	2024/7/22	符合标准要求	 A worker in a red safety suit and helmet is working on a blue structure, possibly a piece of machinery or a container. The worker is holding a tool or cable. The date 2024/07/12 is visible in the bottom right corner of the photo.
312	GX-B1310/21-2-24232	2024/7/22	符合标准要求	 A worker in a red safety suit and helmet is standing on a platform or walkway. The worker is looking towards the camera. The date 2024/07/12 is visible in the bottom right corner of the photo.
313	GX-B1427/21-2-24232	2024/7/22	符合标准要求	 A worker in a red safety suit and helmet is standing near a red and white striped barrier. The worker is looking towards the camera. The date 2024/07/12 is visible in the bottom right corner of the photo.

314	GX-B1328/20-2-24073	2024/7/23	本次共检绝缘胶垫5块，5块所检项目合格。	
315	GX-B1521/20-2-24008	2024/7/23	所检项目合格。	
316	GX-B1521/20-2-24009	2024/7/23	所检项目合格。	

317	GX-B1521/20-2-24010	2024/7/23	所检项目合格。	
318	GX-B1521/20-2-24011	2024/7/23	所检项目合格。	
319	GX-B1321/20-2-24482~24489	2024/7/23	所检项目合格	

320	GX-B1328/20-2-24066	2024/7/23	所检项目合格	
321	GX-B1328/20-2-24067	2024/7/23	所检项目合格	
322	GX-B1328/20-2-24068	2024/7/23	所检项目合格	

323	GX-B1328/20-2-24069	2024/7/23	所检项目合格	
324	GX-B1328/20-2-24070	2024/7/23	所检项目合格	
325	GX-B1416/22-2-24016	2024/7/24	综合判定：合格。	

326	GX-B1416/22-2-24018	2024/7/24	综合判定：合格。	 <p>2024/07/09</p>
327	GX-B1451/20-2-24446~24449	2024. 7. 24	本次共检高压断路器4台，4台所检项目合格。	 <p>2024/07/04</p>
328	GX-B1322/21-2-24246~24247	2024. 7. 23	本次共检验电力电缆2条，2条所检项目合格。	 <p>2024/06/29</p>

329	GX-B1322/21-2-24248~24249	2024. 7. 23	本次共检验电力电缆2条，2条所检项目合格。	
330	GX-B1451/20-2-24450~24459	2024. 7. 24	本次共检高压开关柜10台，10台所检项目合格。	
331	GX-B1451/20-2-24460~24477	2024. 7. 24	本次共检高压开关柜18台，18台所检项目合格。	

332	GX-B1598-24-2-24150	2024. 7. 25	实测钢丝绳有效截面积损失百分比最大为1.10%，小于5%为正常。	
333	GX-B1598-24-2-24151	2024. 7. 25	实测钢丝绳有效截面积损失百分比最大为0.89%，小于5%为正常。	
334	GX-B1598-24-2-24152	2024. 7. 25	实测钢丝绳有效截面积损失百分比最大为0.98%，小于5%为正常。	

335	GX-B1598-24-2-24153	2024. 7. 25	实测钢丝绳有效截面积损失百分比最大为1.04%，小于5%为正常。	
336	GX-B1598-24-2-24154	2024. 7. 25	实测钢丝绳有效截面积损失百分比最大为1.16%，小于5%为正常。	
337	GX-B1598-24-2-24155	2024. 7. 25	实测钢丝绳有效截面积损失百分比最大为0.86%，小于5%为正常。	

338	GX-B1309/21-2-24013	2024. 7. 25	所检项目合格。	
339	GX-B1500/21-2-24064	2024. 7. 25	综合判定：合格。	
340	GX-B1500/21-2-24065	2024. 7. 25	综合判定：合格。	

341	GX-B1500/21-2-24066	2024. 7. 25	综合判定：合格。	 A photograph of an industrial setting. A worker in a blue uniform and red hard hat is standing near a large green machine. The machine has a sign that says '冷水器' (Chilled Water Chiller). The floor is yellow and green. The date '2024.7.25' is visible in the bottom right corner.
342	GX-B1500/21-2-24067	2024. 7. 25	综合判定：合格。	 A photograph of an industrial setting. A worker in a blue uniform and red hard hat is standing near a large green machine. The machine has a sign that says '冷水器' (Chilled Water Chiller). The floor is yellow and green. The date '2024.7.25' is visible in the bottom right corner.
343	GX-B1500/21-2-24068	2024. 7. 25	综合判定：合格。	 A photograph of an industrial setting. A worker in a blue uniform and red hard hat is standing near a large green machine. The machine has a sign that says '冷水器' (Chilled Water Chiller). The floor is yellow and green. The date '2024.7.25' is visible in the bottom right corner.


344	GX-B1500/21-2-24069	2024. 7. 25	综合判定：合格。	
345	GX-B1500/21-2-24070	2024. 7. 25	综合判定：合格。	
346	GX-B1310/21-2-24221	2024/7/25	符合标准要求。	

347	GX-B1310/21-2-24222	2024/7/25	符合标准要求。	 <p>2024/07/25</p>
348	GX-B1310/21-2-24223	2024/7/25	符合标准要求。	 <p>2024/07/25</p>
349	GX-B1310/21-2-24224	2024/7/25	符合标准要求。	 <p>2024/06/28</p>

350	GX-B1310/21-2-24225	2024/7/25	符合标准要求。	
351	GX-B1310/21-2-24226	2024/7/25	符合标准要求。	
352	GX-B1310/21-2-24200	2024/7/25	符合标准要求。	


353	GX-B1310/21-2-24201	2024/7/25	符合标准要求。	 <p>2024/06/26</p>
354	GX-B1310/21-2-24202	2024/7/25	符合标准要求。	 <p>2024/06/26</p>
355	GX-B1310/21-2-24203	2024/7/25	符合标准要求。	 <p>2024/06/26</p>

356	GX-B1310/21-2-24204	2024/7/25	符合标准要求。	
357	GX-B1310/21-2-24205	2024/7/25	符合标准要求。	
358	GX-B1310/21-2-24206	2024/7/25	符合标准要求。	

359	GX-B1310/21-2-24207	2024/7/25	符合标准要求。	 <p>2024/07/26</p>
360	GX-B1310/21-2-24208	2024/7/25	符合标准要求。	 <p>2024/07/26</p>
361	GX-B1310/21-2-24209	2024/7/25	符合标准要求。	 <p>2024/07/26</p>

362	GX-B1310/21-2-24210	2024/7/25	符合标准要求。	 A worker in a blue uniform and red helmet is operating a piece of yellow machinery outdoors. The background shows a hilly landscape under a blue sky. A timestamp '2024/06/26' is visible in the bottom right corner of the image.
363	GX-B1310/21-2-24211	2024/7/25	符合标准要求。	 A worker in a blue uniform and red helmet is standing on a metal platform or walkway. In the background, there are blue signs with Chinese characters. A timestamp '2024/06/26' is visible in the bottom right corner of the image.
364	GX-B1598/24-2-24134	2024/7/25	实测钢丝绳有效截面积损失百分比最大为4.70%，小于5%为正常。	 A worker wearing a high-visibility vest and a headlamp is inspecting a cable in a dark environment. The worker is holding a clipboard. A timestamp '2024/07/01' is visible in the bottom right corner of the image.

365	GX-B1598/24-2-24135	2024/7/25	实测钢丝绳有效截面积损失百分比最大为4.46%，小于5%为正常。	
366	GX-B1598/24-2-24136	2024/7/25	实测钢丝绳有效截面积损失百分比最大为2.80%，小于5%为正常。	
367	GX-B1598/24-2-24137	2024/7/25	实测钢丝绳有效截面积损失百分比最大为2.55%，小于5%为正常。	

368	GX-B1598/24-2-24138	2024/7/25	实测钢丝绳有效截面积损失百分比最大为4.85%，小于5%为正常。	 <p>2024.07.25</p>
369	GX-B1598/24-2-24139	2024/7/25	实测钢丝绳有效截面积损失百分比最大为4.21%，小于5%为正常。	 <p>2024.07.25</p>
370	GX-B1598/24-2-24140	2024/7/25	实测钢丝绳有效截面积损失百分比最大为4.03%，小于5%为正常。	 <p>2024.07.02</p>

371	GX-B1598/24-2-24141	2024/7/25	实测钢丝绳有效截面积损失百分比最大为4.40%，小于5%为正常。	
372	GX-B1598/24-2-24142	2024/7/25	实测钢丝绳有效截面积损失百分比最大为2.72%，小于5%为正常。	
373	GX-B1598/24-2-24143	2024/7/25	实测钢丝绳有效截面积损失百分比最大为2.46%，小于5%为正常。	

374	GX-B1310/21-2-24212	2024/7/25	符合标准要求。	
375	GX-B1310/21-2-24213	2024/7/25	符合标准要求。	
376	GX-B1310/21-2-24214	2024/7/25	符合标准要求。	

377	GX-B1310/21-2-24215	2024/7/25	符合标准要求。	
378	GX-B1310/21-2-24216	2024/7/25	符合标准要求。	
379	GX-B1310/21-2-24217	2024/7/25	符合标准要求。	

380	GX-B1310/21-2-24218	2024/7/25	符合标准要求。	
381	GX-B1310/21-2-24219	2024/7/25	符合标准要求。	
382	GX-B1310/21-2-24220	2024/7/25	符合标准要求。	

383	GX-B1495/20-2-241290~241293	2024. 7. 26	所检项目合格	
384	GX-B1495/20-2-241294~241297	2024. 7. 26	所检项目合格	