

序号	报告编号	发布日期	结论	影像资料
157	GX-B1427/21-6-24052	2024/7/16	符合标准要求	 A photograph showing a worker in a red helmet and safety harness working on a large, dark, cylindrical industrial component. The worker is positioned on the left side of the frame, reaching towards the component. The background shows an industrial setting with metal structures. A timestamp '2024 06 17' is visible in the bottom right corner of the image.
158	GX-B1427/21-6-24053	2024/7/16	符合标准要求	 A photograph showing a worker in a red helmet and safety harness working on a large, dark, cylindrical industrial component. The worker is positioned on the right side of the frame, reaching towards the component. The background shows an industrial setting with metal structures. A timestamp '2024 06 15' is visible in the bottom right corner of the image.

159	GX-B1427/21-6-24054	2024/7/16	符合标准要求		
160	GX-B1427/21-6-24055	2024/7/16	符合标准要求		
161	GX-B1310/21-6-24169	2024/7/16	符合标准要求		

162	GX-B1310/21-6-24170	2024/7/16	符合标准要求	
163	GX-B1310/21-6-24171	2024/7/16	符合标准要求	
164	GX-B1310/21-6-24172	2024/7/16	符合标准要求	

165	GX-B1310/21-6-24173	2024/7/16	符合标准要求	 <p>2024.06.15</p>	
166	GX-B1310/21-6-24174	2024/7/16	符合标准要求	 <p>2024.06.15</p>	
167	GX-B1310/21-6-24175	2024/7/16	符合标准要求	 <p>2024.06.16</p>	




168	GX-B1310/21-6-24176	2024/7/16	符合标准要求	
169	GX-B1310/21-6-24177	2024/7/16	符合标准要求	
170	GX-B1310/21-6-24178	2024/7/16	符合标准要求	

171	GX-B1310/21-6-24148	2024/7/18	符合标准要求	 <p>2024 05 22</p>
172	GX-B1310/21-6-24149	2024/7/18	符合标准要求	 <p>2024 05 21</p>
173	GX-B1310/21-6-24152	2024/7/18	符合标准要求	 <p>2024 05 20</p>




174	GX-B1310/21-6-24150	2024/7/18	符合标准要求	 <p>2024 05 21</p>
175	GX-B1310/21-6-24151	2024/7/18	符合标准要求	 <p>2024 05 21</p>
176	GX-B1310/21-6-24153	2024/7/18	符合标准要求	 <p>2024 05 20</p>

177	GX-B1310/21-6-24154	2024/7/18	符合标准要求	 <p>2024 05 20</p>	
178	GX-B1310/21-6-24155	2024/7/18	符合标准要求	 <p>2024 05 22</p>	
179	GX-B1310/21-6-24156	2024/7/18	符合标准要求	 <p>2024 05 22</p>	

180	GX-B1310/21-6-24157	2024/7/18	符合标准要求	 <p>2024 05 22</p>	
181	GX-B1310/21-6-24158	2024/7/18	符合标准要求	 <p>2024 05 22</p>	
182	GX-B1310/21-6-24159	2024/7/18	符合标准要求	 <p>2024 05 22</p>	

183	GX-B1310/21-6-24160	2024/7/18	符合标准要求		
184	GX-B1310/21-6-24161	2024/7/18	符合标准要求		
185	GX-B1310/21-6-24162	2024/7/18	符合标准要求		

186	GX-B1310/21-6-24163	2024/7/18	符合标准要求		
187	GX-B1310/21-6-24164	2024/7/18	符合标准要求		
188	GX-B1310/21-6-24165	2024/7/18	符合标准要求		

189	GX-B1598/21-6-24056	2024/7/19	实测钢丝绳有效截面积损失百分比最大为0.50%，小于5%为正常。	
190	GX-B1598/21-6-24057	2024/7/19	实测钢丝绳有效截面积损失百分比最大为0.53%，小于5%为正常。	
191	GX-B1598/21-6-24058	2024/7/19	实测钢丝绳有效截面积损失百分比最大为0.56%，小于5%为正常。	

192	GX-B1598/21-6-24059	2024/7/19	实测钢丝绳有效截面积损失百分比最大为0.54%，小于5%为正常。	
193	GX-B1598/21-6-24060	2024/7/19	实测钢丝绳有效截面积损失百分比最大为1.58%，小于5%为正常。	
194	GX-B1598/21-6-24061	2024/7/19	实测钢丝绳有效截面积损失百分比最大为1.65%，小于5%为正常。	

195	GX-B1598/21-6-24062	2024/7/19	实测钢丝绳有效截面积损失百分比最大为1.58%，小于5%为正常。	 <p>2024 05 21</p>
196	GX-B1427/21-6-24062	2024/7/22	符合标准要求	 <p>2024 06 06</p>
197	GX-B1310/21-6-24187	2024/7/22	符合标准要求	 <p>2024 06 04</p>

198	GX-B1310/21-6-24188	2024/7/22	符合标准要求	
199	GX-B1310/21-6-24189	2024/7/22	符合标准要求	
200	GX-B1310/21-6-24190	2024/7/22	符合标准要求	

201	GX-B1310/21-6-24191	2024/7/22	符合标准要求		
202	GX-B1310/21-6-24192	2024/7/22	符合标准要求		
203	GX-B1310/21-6-24193	2024/7/22	符合标准要求		

204	GX-B1310/21-6-24194	2024/7/22	符合标准要求	 A worker in a blue uniform and red helmet is working on a railway track. The worker is standing on the tracks, and there is a large metal component on the track. The background shows a green hillside. The date '2024 06 05' is visible in the bottom right corner of the image.
205	GX-B1310/21-6-24195	2024/7/22	符合标准要求	 A worker in a blue uniform and red helmet is working on a large industrial machine. The worker is leaning over the machine, and there is a large red component. The background shows a white wall with some posters. The date '2024 06 05' is visible in the bottom right corner of the image.
206	GX-B1310/21-6-24196	2024/7/22	符合标准要求	 A worker in a blue uniform and red helmet is working on a large industrial machine. The worker is standing on a blue structure, and there is a large black wheel. The background shows a white wall. The date '2024 06 05' is visible in the bottom right corner of the image.

207	GX-B1310/21-6-24197	2024/7/22	符合标准要求	 <p>2024 06 06</p>
208	GX-B1310/21-6-24198	2024/7/22	符合标准要求	 <p>2024 06 06</p>
209	GX-B1310/21-6-24199	2024/7/22	符合标准要求	 <p>2024 06 06</p>

210	GX-B1310/21-6-24200	2024/7/22	符合标准要求	
211	GX-B1310/21-6-24201	2024/7/22	符合标准要求	
212	GX-B1305/21-6-24021	2024/7/23	综合判定合格	

213	GX-B1305/21-6-24019	2024/7/23	综合判定合格		
214	GX-B1303/21-6-24016	2024/6/21	综合判定合格		
215	GX-B1303/21-6-24022	2024/7/18	综合判定合格		

216	GX-B1303/21-6-24023	2024/7/18	综合判定合格	 <p>2024 06 04</p>	
217	GX-B1303/21-6-24024	2024/7/18	综合判定合格	 <p>2024 06 05</p>	
218	GX-B1303/21-6-24025	2024/7/18	综合判定合格	 <p>2024 06 05</p>	