

序号	报告编号	发布日期	结论	影像资料
185	GX-B1522/20-Y-24098	2024年7月19日	所检项目合格。	
186	GX-B1522/20-Y-24102	2024年7月19日	所检项目合格。	

187	GX-B1428/21-Y- 24142	2024年7月16日	无缺陷迹痕显示。	
188	GX-B1310/21-Y- 24143	2024年7月17日	符合标准要求。	

189	GX-B1310/21-Y- 24144	2024年7月17日	符合标准要求。	 <p>2022/6/1</p>
190	GX-B1495/20-Y-241611~241615	2024年7月22日	本次共检高压开关设备5台，5台高压开关设备所检项目合格	 <p>2024/5/28</p>

191	GX-B1310/21-Y- 24146	2024年7月17日	符合标准要求。	 <p>符合标准要求。</p>
192	GX-B1428/21-Y- 24141	2024年7月16日	无缺陷迹痕显示。	 <p>无缺陷迹痕显示。</p>

193	GX-B1310/21-Y- 24145	2024年7月17日	符合标准要求。	
194	GX-B1310/21-Y- 24141	2024年7月16日	符合标准要求。	

195	GX-B1310/21-Y- 24142	2024年7月17日	符合标准要求。	
196	GX-B1499/23-Y-24043	2024年7月22日	实测流量为71.7m <sup>3</sup> /h。 。	

197	GX-B1499/23-Y-24044	2024年7月22日	实测流量为68.4m <sup>3</sup> /h。 。	
198	GX-B1499/23-Y-24045	2024年7月22日	实测流量为63.6m <sup>3</sup> /h。 。	

199	GX-B1499/23-Y-24047	2024年7月22日	所检项目合格。	
200	GX-B1499/23-Y-24046	2024年7月22日	所检项目合格。	



201	GX-B1499/23-Y-24048	2024年7月22日	所检项目合格。	
202	GX-B1499/23-Y-24042	2024年7月22日	实测流量为62.3m <sup>3</sup> /h。	

203	GX-B1559/22-Y-24025	2024年7月23日	所检项目合格。	 <p>2024/7/20</p>
204	GX-B1521/20-Y-24521	2024年7月23日	所检项目合格。	 <p>2024/7/18</p>

205	GX-B1521/20-Y-24522	2024年7月23日	所检项目合格。	
206	GX-B1521/20-Y-24523	2024年7月23日	所检项目合格。	

207	GX-B1521/20-Y-24524	2024年7月23日	所检项目合格。	
208	GX-B1521/20-Y-24525	2024年7月23日	所检项目合格。	

209	GX-B1521/20-Y-24526	2024年7月23日	所检项目合格。	
210	GX-B1521/20-Y-24527	2024年7月23日	所检项目合格。	

211	GX-B1521/20-Y-24528	2024年7月23日	所检项目合格。	
212	GX-B1521/20-Y-24529	2024年7月23日	所检项目合格。	



213	GX-B1521/20-Y-24530	2024年7月23日	所检项目合格。	
214	GX-B1521/20-Y-24531	2024年7月23日	所检项目合格。	

215	GX-B1521/20-Y-24532	2024年7月23日	所检项目合格。	 A yellow tracked excavator is shown in an outdoor setting, likely a construction or mining site. The excavator is positioned on a dirt surface, and its arm is extended. A person in a yellow safety vest and hard hat stands next to the excavator for scale. The background shows a large, light-colored rock face. A yellow timestamp "2024/7/16" is visible in the bottom right corner of the photo.
216	GX-B1521/20-Y-24533	2024年7月23日	所检项目合格。	 A red tracked excavator is shown in an outdoor setting, likely a construction or mining site. The excavator is positioned on a dirt surface, and its arm is extended. Two people in yellow safety vests and hard hats stand next to the excavator for scale. The background shows a large, light-colored rock face. A yellow timestamp "2024/7/16" is visible in the bottom right corner of the photo.



217	GX-B1521/20-Y-24534	2024年7月23日	所检项目合格。	
218	GX-B1521/20-Y-24535	2024年7月23日	所检项目合格。	

219	GX-B1521/20-Y-24536	2024年7月23日	所检项目合格。	 A yellow tracked excavator is shown at a construction site. The excavator's arm is raised, and its bucket is positioned over a pile of dirt. A person wearing a yellow safety vest and a red hard hat stands next to the excavator. The background shows a clear blue sky and a sandy area. A yellow timestamp "2024/7/16" is visible in the bottom right corner of the image.
220	GX-B1521/20-Y-24537	2024年7月23日	所检项目合格。	 A yellow tracked excavator is shown at a construction site. The excavator's arm is raised, and its bucket is positioned over a pile of dirt. A person wearing a yellow safety vest and a red hard hat stands next to the excavator. The background shows a clear blue sky and a sandy area. A yellow timestamp "2024/7/17" is visible in the bottom right corner of the image.

221	GX-B1521/20-Y-24538	2024年7月23日	所检项目合格。	
222	GX-B1521/20-Y-24539	2024年7月23日	所检项目合格。	

223	GX-B1521/20-Y-24540	2024年7月23日	所检项目合格。	
224	GX-B1521/20-Y-24541	2024年7月23日	所检项目合格。	

225	GX-B1521/20-Y-24542	2024年7月23日	所检项目合格。	
226	GX-B1521/20-Y-24543	2024年7月23日	所检项目合格。	

227	GX-B1521/20-Y-24544	2024年7月23日	所检项目合格。	 A yellow tracked excavator is shown at a construction site. A person in a high-visibility vest stands next to the machine. The date stamp '2024/7/17' is visible in the bottom right corner of the photo.
228	GX-B1521/20-Y-24545	2024年7月23日	所检项目合格。	 A yellow tracked excavator is shown at a construction site. A person in a high-visibility vest stands next to the machine. The date stamp '2024/7/17' is visible in the bottom right corner of the photo.

229	GX-B1521/20-Y-24546	2024年7月23日	所检项目合格。	 A yellow tracked excavator is shown in a desert-like environment. The excavator's arm is raised, and its bucket is positioned over a pile of rubble. A person in a high-visibility vest stands near the machine. A yellow timestamp '2024/7/17' is visible in the bottom right corner of the photo.
230	GX-B1521/20-Y-24547	2024年7月23日	所检项目合格。	 A yellow tracked excavator is shown in a desert-like environment. The excavator's arm is raised, and its bucket is positioned over a pile of rubble. A person in a high-visibility vest stands near the machine. A yellow timestamp '2024/7/17' is visible in the bottom right corner of the photo.

231	GX-B1539/22-Y-24284	2024年7月23日	所检项目合格。	 A photograph of a yellow XCMG MF1020 wheel loader. Two workers wearing high-visibility vests and hard hats are standing next to the machine. The loader has 'XCMG' and 'MF1020' printed on its side. A yellow timestamp '2024/7/15' is visible in the bottom right corner of the image.
232	GX-B1539/22-Y-24285	2024年7月23日	所检项目合格。	 A photograph of a yellow XCMG wheel loader. Two workers wearing high-visibility vests and hard hats are standing next to the machine. The loader has 'XCMG' and 'MF1020' printed on its side. A yellow timestamp '2024/7/15' is visible in the bottom right corner of the image.



233	GX-B1539/22-Y-24286	2024年7月23日	所检项目合格。	
234	GX-B1539/22-Y-24287	2024年7月23日	所检项目合格。	

235	GX-B1499/23-Y-24049	2024年7月23日	所检项目合格。	
236	GX-B1499/23-Y-24050	2024年7月23日	所检项目合格。	

237	GX-B1499/23-Y-24051	2024年7月23日	所检项目合格。	
238	GX-B1499/23-Y-24052	2024年7月23日	所检项目合格。	

239	GX-B1499/23-Y-24053	2024年7月23日	所检项目合格。	 A photograph showing a worker in a red safety suit and helmet standing in an industrial tunnel. The worker is holding a device, possibly a tablet or a specialized tool. In the background, there are large pipes and a yellow warning sign with a triangle and Chinese characters. The date '2024/7/18' is visible in the bottom right corner of the photo.
240	GX-B1499/23-Y-24054	2024年7月23日	所检项目合格。	 A photograph showing two workers in red safety suits and helmets in an industrial tunnel. One worker is holding a device, possibly a tablet or a specialized tool. The background shows large pipes and industrial equipment. The date '2024/7/18' is visible in the bottom right corner of the photo.

241	GX-B1495/20-Y-241616~241630	2024年7月24日	本次共检高压防爆开关15台，15台高压防爆开关所检项目	
242	GX-B1522/20-Y-24099	2024年7月15日	所检项目合格。	

243	GX-B1522/20-Y-24100	2024年7月15日	所检项目合格。	
244	GX-B1547/20-Y-24257~24263	2024年7月24日	本次共检继电保护装置7台，7台继电保护装置所检项目合格。	

245	GX-B1495/20-Y-241481~241485	2024年7月24日	本次共检高压交流断路器5台，5台高压交流断路器所检项目合格。	 A photograph showing a worker in a white uniform and red helmet working on high-voltage equipment. The worker is standing on a platform, and the equipment is illuminated by a bright light. A yellow timestamp '2024/7/4' is visible in the bottom left corner of the image.
246	GX-B1495/20-Y-241494~241504	2024年7月24日	本次共检高压开关柜11台，11台高压开关柜所检项目合格。	 A photograph showing a worker in a white uniform and red helmet working on a high-voltage switchgear cabinet. The worker is focused on the internal components, which are densely packed with blue and white wires. A yellow timestamp '2024/7/4' is visible in the bottom left corner of the image.



247	GX-B1495/20-Y-241486~241493	2024年7月24日	本次共检高压开关柜8台，8台高压开关柜所检项目合格。	
248	GX-B1495/20-Y-241505~241518	2024年7月24日	本次共检高压开关柜14台，14台高压开关柜所检项目合格。	



249	GX-B1495/20-Y-241594~241606	2024年7月24日	本次共检高压防爆开关13台，13台高压防爆开关所检项目合格。 。	
250	GX-B1495/20-Y-241563~241576	2024年7月24日	本次共检高压防爆开关14台，14台高压防爆开关所检项目合格。 。	

251	GX-B1521/20-Y-24548	2024年7月25日	所检项目合格。	
252	GX-B1521/20-Y-24549	2024年7月25日	所检项目合格。	

253	GX-B1521/20-Y-24550	2024年7月25日	所检项目合格。	
254	GX-B1521/20-Y-24551	2024年7月25日	所检项目合格。	

255	GX-B1521/20-Y-24552	2024年7月25日	所检项目合格。	
256	GX-B1521/20-Y-24553	2024年7月25日	所检项目合格。	

257	GX-B1521/20-Y-24554	2024年7月25日	所检项目合格。	
258	GX-B1521/20-Y-24555	2024年7月25日	所检项目合格。	

259	GX-B1521/20-Y-24556	2024年7月25日	所检项目合格。	
260	GX-B1521/20-Y-24557	2024年7月25日	所检项目合格。	

261	GX-B1521/20-Y-24558	2024年7月25日	所检项目合格。	
262	GX-B1495/20-Y-241519~241540	2024年7月25日	本次共检高压防爆开关22台，22台高压防爆开关所检项目合格。 。	



263	GX-B1495/20-Y-241541~241553	2024年7月25日	本次共检高压防爆开关13台，13台高压防爆开关所检项目合格。 。	 <p>2024/7/7</p>
264	GX-B1495/20-Y-241554~241562	2024年7月25日	本次共检高压防爆开关9台，9台高压防爆开关所检项目合格。	 <p>2024/7/8</p>



265	GX-B1495/20-Y-241577~241593	2024年7月25日	本次共检高压防爆开关17台，17台高压防爆开关所检项目合格。 。	
266	GX-B1495/20-Y-241631~241634	2024年7月25日	本次共检高压防爆开关4台，4台高压防爆开关所检项目合格。	

267	GX-B1522/20-Y-24103	2024年7月26日	所检项目合格。	
268	GX-B1556/22-Y-24021	2024年7月26日	所检项目合格。	

269	GX-B1556/22-Y-24022	2024年7月26日	所检项目合格。	 A yellow tracked bulldozer is parked on a dirt surface in a desert-like environment. Two workers wearing high-visibility vests and hard hats stand in front of the machine. The date '2024/7/19' is visible in the bottom right corner of the photo.
270	GX-B1310/21-Y-24148	2024年7月25日	符合标准要求。	 A worker wearing a white uniform, a red hard hat, and gloves is using a handheld device, possibly a scanner or detector, on a metal grate. The date '2024/7/25' is visible in the bottom left corner of the photo.

271	GX-B1310/21-Y-24149	2024年7月25日	符合标准要求。	
272	GX-B1310/21-Y-24150	2024年7月25日	符合标准要求。	