


序号	报告编号	发布日期	结论	影像资料
385	GX-B1301/23-2-24005	2024/7/25	综合判定:合格。	 <p>2024/07/11</p>
386	GX-B1301/23-2-24006	2024/7/25	综合判定:合格。	 <p>2024/07/11</p>

387	GX-B1415/22-2-24020	2024. 7. 26	综合判定：合格。	
388	GX-B1415/22-2-24021	2024. 7. 26	综合判定：合格。	

389	GX-B1415/22-2-24019	2024. 7. 27	综合判定：合格。	
390	GX-B1415/22-2-24022	2024. 7. 27	综合判定：合格。	

391	GX-B1415/22-2-24023	2024. 7. 27	综合判定：合格。	
392	GX-B1415/22-2-24024	2024. 7. 27	综合判定：合格。	

393	GX-B1415/22-2-24025	2024. 7. 27	综合判定：合格。	 <p>2024/7/18</p>
394	GX-B1301/23-2-24003	2024/7/31	综合判定：合格。	 <p>2024/7/31</p>

395	GX-B1301/23-2-24004	2024/7/31	综合判定:合格。	 A photograph showing two workers in a factory environment. They are wearing red hard hats and light-colored work clothes. They are standing next to large, green industrial machinery. One worker is leaning over the machine, while the other stands nearby. The background shows a typical industrial setting with concrete walls and overhead structures. A timestamp '2024/07/12' is visible in the bottom right corner of the image.
396	GX-B1310/21-2-24251	2024/7/29	符合标准要求。	 A photograph of a worker in a dark environment, likely a tunnel or underground facility. The worker is wearing a red hard hat and a dark jacket with reflective stripes. They are using a flashlight to inspect a piece of machinery or equipment. The scene is dimly lit, with the primary light source being the worker's flashlight. A timestamp '2024/06/19' is visible in the bottom right corner of the image.

397	GX-B1310/21-2-24238	2024/7/25	符合标准要求。		 <p>2024/7/16</p>	
398	GX-B1310/21-2-24239	2024/7/25	符合标准要求。		 <p>2024/7/16</p>	