

序号	报告编号	发布日期	结论	影像资料
302	GX-B1361/22-A-24727	2024/7/26	合格	 A photograph showing two men in light-colored work shirts and dark trousers working in a workshop. They are positioned around a large, light-colored industrial machine. One man is on the left, looking towards the machine, while the other is on the right, looking down at something in his hands. The machine has a tray with several rectangular objects on it. A yellow timestamp '2024/7/24' is visible in the bottom right corner of the image.
303	GX-B1362/23-A-24292	2024/7/29	合格	 A photograph showing two men in light-colored work shirts and dark trousers working in a workshop. They are positioned around a large, light-colored industrial machine. One man is on the left, looking towards the machine, while the other is on the right, looking down at something in his hands. The machine has a tray with several rectangular objects on it. A yellow timestamp '2024/7/12' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
304	GX-B1361/22-A-24728	2024/7/29	合格	
305	GX-B1361/22-A-24729	2024/7/29	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
306	GX-B1361/22-A-24730	2024/7/29	所检项目合格	
307	GX-B1361/22-A-24731	2024/7/29	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
308	GX-B1361/22-A-24732	2024/7/29	所检项目合格	
309	GX-B1361/22-A-24733	2024/7/29	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
310	GX-B1361/22-A-24734	2024/7/29	合格	
311	GX-B1361/22-A-24735	2024/7/29	合格	

序号	报告编号	发布日期	结论	影像资料
312	GX-B1361/22-A-24707	2024/7/29	所检项目合格	
313	GX-B1361/22-A-24708	2024/7/29	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
314	GX-B1361/22-A-24709	2024/7/29	所检项目合格	
315	GX-B1361/22-A-24710	2024/7/29	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
316	GX-B1361/22-A-24711	2024/7/29	不合格	
317	GX-B1361/22-A-24712	2024/7/29	不合格	

序号	报告编号	发布日期	结论	影像资料
318	GX-B1361/22-A-24713	2024/7/29	所检项目合格	
319	GX-B1361/22-A-24714	2024/7/29	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
320	GX-B1361/22-A-24715	2024/7/29	所检项目合格	
321	GX-B1361/22-A-24716	2024/7/29	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
322	GX-B1361/22-A-24717	2024/7/29	所检项目合格	
323	GX-B1361/22-A-24718	2024/7/29	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
324	GX-B1361/22-A-24723	2024/7/29	合格	
325	GX-B1361/22-A-24724	2024/7/29	合格	

序号	报告编号	发布日期	结论	影像资料
326	GX-B1361/22-A-24725	2024/7/29	合格	
327	GX-B1361/22-A-24726	2024/7/29	合格	

序号	报告编号	发布日期	结论	影像资料
328	GX-B1362/23-A-24293	2024/7/29	合格	
329	GX-B1362/23-A-24294	2024/7/29	合格	

序号	报告编号	发布日期	结论	影像资料
330	GX-B1362/23-A-24297	2024/7/29	所检项目合格	
331	GX-B1362/23-A-24298	2024/7/29	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
332	GX-B1362/23-A-24299	2024/7/29	所检项目合格	
333	GX-B1362/23-A-24300	2024/7/29	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
334	GX-B1362/23-A-24301	2024/7/29	所检项目合格	 A photograph showing a male worker in a light-colored short-sleeved shirt operating a lathe machine in a workshop. The machine is a large, industrial-grade lathe with a prominent wooden bed. The worker is leaning over the machine, focused on his work. In the background, another worker is partially visible. The date '2024/7/20' is printed in yellow in the bottom right corner of the image.
335	GX-B1362/23-A-24302	2024/7/29	所检项目合格	 A photograph showing two male workers in light-colored short-sleeved shirts operating a lathe machine in a workshop. They are both wearing gloves and are focused on their work. The machine is a large, industrial-grade lathe with a wooden bed. The date '2024/7/20' is printed in yellow in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
336	GX-B1362/23-A-24303	2024/7/29	所检项目合格	
337	GX-B1362/23-A-24304	2024/7/29	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
338	GX-B1362/23-A-24305	2024/7/29	所检项目合格	
339	GX-B1362/23-A-24306	2024/7/31	合格	

序号	报告编号	发布日期	结论	影像资料
340	GX-B1361/22-A-24719	2024/7/31	所检项目合格	
341	GX-B1361/22-A-24720	2024/7/31	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
342	GX-B1361/22-A-24721	2024/7/31	所检项目合格	
343	GX-B1361/22-A-24722	2024/7/31	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
344	GX-B1361/22-A-24736	2024/7/31	所检项目合格	
345	GX-B1361/22-A-24737	2024/7/31	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
346	GX-B1361/22-A-24738	2024/7/31	所检项目合格	
347	GX-B1361/22-A-24739	2024/7/31	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
348	GX-B1361/22-A-24740	2024/7/31	所检项目合格	 A photograph showing two men in light-colored work shirts operating a large industrial machine in a workshop. The man on the right is wearing gloves and appears to be adjusting or working on a component. The man on the left is observing. The machine is a complex piece of equipment with various rollers and guides. A yellow timestamp '2024/7/26' is visible in the bottom right corner of the image.
349	GX-B1361/22-A-24747	2024/7/30	合格	 A photograph showing two men in light-colored work shirts operating a large industrial machine in a workshop. The man on the right is wearing gloves and appears to be adjusting or working on a component. The man on the left is observing. The machine is a complex piece of equipment with various rollers and guides. A yellow timestamp '2024/7/4' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
350	GX-B1361/22-A-24748	2024/7/31	不合格	