

序号	报告编号	发布日期	结论	影像资料
1	GX-B1328/20-Y-24058	2024年8月2日	本次共检绝缘胶垫 10块，所检项目合格。	
2	GX-B1310/21-Y-24151	2024年8月2日	符合标准要求。	

3	GX-B1328/20-Y-24059	2024年8月2日	所检项目合格。	
4	GX-B1328/20-Y-24060	2024年8月2日	所检项目合格。	

5	GX-B1328/20-Y-24061	2024年8月2日	所检项目合格。	
6	GX-B1328/20-Y-24062	2024年8月2日	所检项目合格。	

7	GX-B1506/21-Y-24001	2024年8月2日	所检项目合格。	
8	GX-B1506/21-Y-24002	2024年8月5日	所检项目合格。	

9	GX-B1506/21-Y-24003	2024年8月5日	所检项目合格。	 <p>A worker wearing a red hard hat and light blue uniform is kneeling on a grey floor in a control room. He is working on a yellow electrical device. In the background, there are electrical panels and a red fire extinguisher. A yellow timestamp '2024/7/12' is visible in the bottom left corner of the photo.</p>
10	GX-B1506/21-Y-24004	2024年8月5日	所检项目合格。	 <p>A worker wearing a red hard hat and light blue uniform is sitting at a desk in a control room, operating a computer monitor. Another worker in a light blue uniform is standing in the background near a window. The worker's uniform has the logo '中检公信' (Zhongjian Gongxin) on the back. A yellow timestamp '2024/7/12' is visible in the bottom left corner of the photo.</p>

11	GX-B1522/20-Y-24104	2024年8月6日	所检项目合格。	
----	---------------------	-----------	---------	---