

序号	报告编号	发布日期	结论	影像资料
59	GX-B1321/20-7-24394~24398	2024. 8. 5	本次共检电力电缆5条，5条电力电缆均合格。	 A worker wearing a blue hard hat and a black shirt is inspecting the interior of an open electrical cabinet. The cabinet contains various cables and components. A timestamp '2024. 8. 25' is visible in the bottom right corner of the photo.
60	GX-B1321/20-7-24399~24402	2024. 8. 5	本次共检电力电缆4条，4条电力电缆均合格。	 Two workers are inspecting an open electrical cabinet. One worker is kneeling and looking at a document, while the other is standing and observing. The cabinet is filled with cables and electrical components. A timestamp '2024. 8. 28' is visible in the bottom right corner of the photo.
61	GX-B1321/20-7-24403	2024. 8. 5	所检项目合格。	 A worker in a black shirt is kneeling and inspecting the interior of an open electrical cabinet. He is looking at a document or a device on the floor. The cabinet contains various cables and electrical components. A timestamp '2024. 8. 29' is visible in the bottom right corner of the photo.

62	GX-B1321/20-7-24404	2024. 8. 5	所检项目合格。	 2024. 5. 30
63	GX-B1321/20-7-24405~24407	2024. 8. 5	本次共检电力电缆 3条，3条电力电缆均合格。	 2024. 6. 1
64	GX-B1321/20-7-24448~24455	2024. 8. 5	本次共检电力电缆 8条，8条电力电缆均合格。	 2024. 6. 7

65	GX-B1321/20-7-24416~24428	2024. 8. 5	本次共检电力电缆 13条，13条电力电缆均 合格。	
66	GX-B1321/20-7-24408~24415	2024. 8. 5	本次共检电力电缆 8条，8条电力电缆均合 格。	
67	GX-B1321/20-7-24384~24393	2024. 8. 5	本次共检电力电缆 10条，10条电力电缆均 合格。	

68	GX-B1321/20-7-24375~24383	2024. 8. 5	本次共检电力电缆 9条，9条电力电缆均合 格。	
69	GX-B1310/21-7-24034	2024. 8. 5	符合标准要求	
70	GX-B1428/21-7-24034	2024. 8. 5	无缺陷痕迹显示	

71	GX-B1310/21-7-24035	2024. 8. 5	符合标准要求			
72	GX-B1428/21-7-24035	2024. 8. 5	无缺陷迹痕显示			
73	GX-B1310/21-7-24038	2024. 8. 5	符合标准要求			

74	GX-B1416/22-7-24025	2024. 8. 6	综合判定：合格。			
----	---------------------	------------	----------	--	---	--