



序号	报告编号	发布日期	结论	影像资料
12	GX-B1523/20-Y-24001	2024年8月7日	所检项目合格。	 <p>2024/7/7</p>
13	GX-B1310/21-Y-24153	2024年8月8日	符合标准要求。	 <p>2024.7.25</p>

14	GX-B1310/21-Y-24154	2024年8月8日	符合标准要求。	
15	GX-B1310/21-Y-24152	2024年8月8日	符合标准要求。	

16	GX-B1521/20-Y-24559	2024年8月9日	所检项目合格。	 A photograph of a yellow SANY excavator at a construction site. Two workers in white uniforms and red hard hats are standing near the machine. A yellow date stamp '2024/8/3' is visible in the bottom right corner of the photo.
17	GX-B1521/20-Y-24560	2024年8月9日	所检项目合格。	 A photograph of a yellow SANY excavator at a construction site. One worker in a white uniform and red hard hat is standing near the machine. A yellow date stamp '2024/8/3' is visible in the bottom right corner of the photo.

18	GX-B1521/20-Y-24561	2024年8月9日	所检项目合格。	 A photograph of a yellow SANY excavator at a construction site. Two workers in safety gear are standing near the machine. A yellow date stamp '2024/8/3' is visible in the bottom right corner of the photo.
19	GX-B1521/20-Y-24562	2024年8月9日	所检项目合格。	 A photograph of a yellow SANY excavator at a construction site, similar to the one above. Two workers in safety gear are standing near the machine. A yellow date stamp '2024/8/3' is visible in the bottom right corner of the photo.

20	GX-B1521/20-Y-24563	2024年8月9日	所检项目合格。	
----	---------------------	-----------	---------	---