


序号	报告编号	发布日期	结论	影像资料
52	GX-B1495/20-3-243900~243917	2024年8月9日	本次共检电流互感器18只，18只电流互感器所检项目合格。	
53	GX-B1495/20-3-243918~243935	2024年8月9日	本次共检电流互感器18只，18只电流互感器所检项目合格。	
54	GX-B1495/20-3-243936~243968	2024年8月9日	本次共检电流互感器33只，33只电流互感器所检项目合格。	

55	GX-B1495/20-3-243969~244013	2024年8月9日	本次共检电流互感器 45只，45只电流互感器所 检项目合格。	
56	GX-B1495/20-3-244014~244066	2024年8月9日	本次共检电流互感器 53只，53只电流互感器所 检项目合格。	
57	GX-B1495/20-3-244067~244109	2024年8月9日	本次共检电流互感器 43只，43只电流互感器所 检项目合格。	

58	GX-B1495/20-3-244200~244218	2024年8月9日	本次共检电流互感器19只，19只电流互感器所检项目合格。	
59	GX-B1495/20-3-244250~244260	2024. 8. 9	所检项目合格。	
60	GX-B1495/20-3-243654~243683	2024. 8. 9	所检项目合格。	

61	GX-B1495/20-3-243684~243719	2024. 8. 9	所检项目合格。	
62	GX-B1495/20-3-243720~243737	2024. 8. 9	所检项目合格。	
63	GX-B1495/20-3-243738~243749	2024. 8. 9	所检项目合格。	

64	GX-B1612/23-3-24005	2024. 8. 9	所检项目合格。	
65	GX-B1612/23-3-24006	2024. 8. 9	所检项目合格。	

66	GX-B1612/23-3-24007	2024. 8. 9	所检项目合格。	
67	GX-B1612/23-3-24008	2024. 8. 9	所检项目合格。	

68	GX-B1612/23-3-24009	2024. 8. 9	所检项目合格。	
69	GX-B1612/23-3-24010	2024. 8. 9	所检项目合格。	

70	GX-B1612/23-3-24011	2024. 8. 9	所检项目合格。	
71	GX-B1612/23-3-24012	2024. 8. 9	所检项目合格。	

72	GX-B1310/21-3-24224	2024年8月9日	符合标准要求。	
73	GX-B1427/21-3-24081	2024年8月9日	符合标准要求。	

74	GX-B1310/21-3- 24209	2024年8月7日	符合标准要求。	
75	GX-B1310/21-3- 24210	2024年8月7日	符合标准要求。	

76	GX-B1310/21-3- 24211	2024年8月7日	符合标准要求。	
77	GX-B1310/21-3-24212	2024年8月7日	符合标准要求。	

78	GX-B1310/21-3-24213	2024年8月7日	符合标准要求。	
79	GX-B1310/21-3-24214	2024年8月7日	符合标准要求。	

80	GX-B1310/21-3- 24206	2024年8月7日	符合标准要求。	
81	GX-B1310/21-3- 24207	2024年8月7日	符合标准要求。	

82	GX-B1310/21-3- 24208	2024年8月7日	符合标准要求。	
83	GX-B1427/21-3-24078	2024年8月7日	符合标准要求。	



84	GX-B1427/21-3-24079	2024年8月7日	符合标准要求。	
85	GX-B1427/21-3-24080	2024年8月7日	符合标准要求。	

86	GX-B1311/21-3-24001	2024年8月13日	<p>副井大罐罐道（东）方形空心钢罐道实测最小壁厚为12.77mm。副井大罐罐道（西）方形空心钢罐道实测最小壁厚为12.65mm。副井小罐罐道（东）方形空心钢罐道实测最小壁厚为11.73mm。副井小罐罐道（西）方形空心钢罐道实测最小壁厚为11.81mm。1#主井主箕斗罐道（卸载侧）方形空心钢罐道实测最小壁厚为15.64mm。1#主井主箕斗罐道（装载侧）方形空心钢罐道实测最小壁厚为15.66mm。1#主井副箕斗罐道（卸载侧）方形空心钢罐道实测最小壁厚为15.66mm。1#主井副箕斗罐道（装载侧）方形空心钢罐道实测最小壁厚为15.55mm。2#主井主箕斗罐道（卸载侧）方形空心钢罐道实测最小壁厚为15.73mm。2#主井主箕斗罐道（装载侧）方形空心钢罐道实测最小壁厚为15.63mm。2#主井副箕斗罐道（卸载侧）方形空心钢罐道实测最小壁厚为16.02mm。2#主井副箕斗罐道（装载侧）方形空心钢罐道实测最小壁厚为15.47mm。</p>	
87	GX-B1311/21-3-24002	2024年8月12日	<p>Φ273×7无缝钢管实测最小壁厚为6.71mm。</p>	

88	GX-B1311/21-3-24003	2024年8月13日	<p>Φ168×7无缝钢管实测最小壁厚为7.32mm。Φ273×9无缝钢管实测最小壁厚为10.24mm。</p>	
89	GX-B1311/21-3-24004	2024年8月13日	<p>Φ219×10无缝钢管实测最小壁厚为9.81mm。</p>	

90	GX-B1311/21-3-24005	2024年8月13日	Φ377×9无缝钢管实测最小壁厚为5.83mm。	 <p>2024.5.30</p>
91	GX-B1311/21-3-24006	2024年8月13日	<p>副井1#排水管（东）Φ377×10无缝钢管实测最小壁厚为10.27mm，Φ377×18无缝钢管实测最小壁厚为18.42mm。副井2#排水管（西）Φ377×10无缝钢管实测最小壁厚为10.22mm，Φ377×18无缝钢管实测最小壁厚为18.34mm。回风井3#排水管Φ377×18无缝钢管实测最小壁厚为18.29mm。回风井4#排水管Φ377×18无缝钢管实测最小壁厚为18.15mm。</p>	 <p>2024.5.31</p>

92	GX-B1310/21-3-24225	2024年8月13日	符合标准要求。	
93	GX-B1310/21-3-24226	2024年8月13日	符合标准要求。	

94	GX-B1310/21-3-24227	2024年8月13日	符合标准要求。	
95	GX-B1310/21-3-24228	2024年8月13日	符合标准要求。	

96	GX-B1310/21-3-24229	2024年8月13日	符合标准要求。	
97	GX-B1310/21-3-24230	2024年8月13日	符合标准要求。	

98	GX-B1310/21-3-24231	2024年8月13日	符合标准要求。	
99	GX-B1310/21-3-24232	2024年8月13日	符合标准要求。	

100	GX-B1310/21-3-24233	2024年8月13日	符合标准要求。	
101	GX-B1522/20-3-24013	2024年8月14日	所检项目合格。	

102	GX-B1522/20-3-24007	2024年8月14日	所检项目合格。	
103	GX-B1522/20-3-24008	2024年8月14日	所检项目合格。	

104	GX-B1522/20-3-24009	2024年8月14日	所检项目合格。	
105	GX-B1522/20-3-24010	2024年8月14日	所检项目合格。	

106	GX-B1522/20-3-24011	2024年8月14日	所检项目合格。	
107	GX-B1522/20-3-24012	2024年8月14日	所检项目合格。	

108	GX-B1321/20-3-241783~241790	2024年8月16日	本次共检电力电缆8条，8条电力电缆所检项目合格。	 A close-up photograph of a worker wearing a red hard hat and safety glasses, focused on inspecting or working on a red electrical cabinet. The worker is wearing a blue uniform. A small timestamp '2024.6.13' is visible in the bottom right corner of the image.
109	GX-B1321/20-3-241767~241775	2024年8月16日	本次共检电力电缆9条，9条电力电缆所检项目合格。	 A photograph of a worker wearing a red hard hat and a blue uniform, kneeling on a green floor. The worker is positioned next to a white electrical cabinet or control panel, appearing to be in the middle of an inspection or maintenance task. A small timestamp '2024.6.12' is visible in the bottom right corner of the image.


110	GX-B1321/20-3-241776~241782	2024年8月16日	本次共检电力电缆7条，7条电力电缆所检项目合格。	 <p>2024.6.13</p>
111	GX-B1495/20-3-244110~244131	2024. 8. 16	所检项目合格。	 <p>2024.5.18</p>

112	GX-B1495/20-3-244132~244155	2024. 8. 16	所检项目合格。	
113	GX-B1495/20-3-244156~244177	2024. 8. 16	所检项目合格。	

114	GX-B1495/20-3-244178~244199	2024. 8. 16	所检项目合格。	
115	GX-B1495/20-3-2244219~244231	2024. 8. 16	所检项目合格。	

116	GX-B1495/20-3-244232~244249	2024. 8. 16	所检项目合格。	
117	GX-B1495/20-3-244499~244512	2024. 8. 16	所检项目合格。	

118	GX-B1495/20-3-244261~244278	2024. 8. 16	所检项目合格。	
119	GX-B1495/20-3-244279~244284	2024. 8. 16	所检项目合格。	

120	GX-B1495/20-3-244285~244324	2024. 8. 16	所检项目合格。	
121	GX-B1495/20-3-244325~244335	2024. 8. 16	所检项目合格。	

122	GX-B1495/20-3-244336~244363	2024. 8. 16	所检项目合格。	
123	GX-B1495/20-3-244364~244392	2024. 8. 16	所检项目合格。	

124	GX-B1495/20-3-244393~244406	2024. 8. 16	所检项目合格。	
125	GX-B1495/20-3-244407~244447	2024. 8. 16	所检项目合格。	

126	GX-B1495/20-3-244448~244492	2024. 8. 16	所检项目合格。	
127	GX-B1495/20-3-244493~244498	2024. 8. 16	所检项目合格。	