

序号	报告编号	发布日期	结论	影像资料
15	GX-B1489/21-F-24063~F-24066	2024. 8. 19	本次共检液压油油样4个，4个油样所检项目合格。	
16	GX-B1378/22-F-24195~F-24196	2024. 8. 19	本次共检空气压缩机油油样2个，2个油样所检项目合格	

17	GX-B1378/22-F-24197	2024. 8. 19	所检项目合格	
18	GX-B1489/21-F-24063~F-24066	2024. 8. 16	本次共检液压油油样4个，4个油样所检项目合格。	

19	GX-B1489/21-F-24067~F-24070	2024. 8. 20	本次共检液压油油样 4个，4个油样所检项 目合格	 A photograph showing two female technicians in a laboratory. They are wearing light blue lab coats with a logo on the back. One technician is standing at a piece of equipment, possibly a spectrophotometer or a similar analytical instrument, and appears to be operating it. The other technician is standing next to her, looking on. The background shows a clean, professional lab environment with a white wall and a blue cabinet. A timestamp '2024.8.16' is visible in the bottom right corner of the photo.
20	GX-B1489/21-F-24071~F-24072	2024. 8. 20	本次共检液压油油样 2个，2个油样所检项 目合格	 A photograph showing two female technicians in a laboratory, similar to the one above. They are wearing light blue lab coats. One technician is standing at a piece of equipment, possibly a spectrophotometer, and appears to be operating it. The other technician is standing next to her, looking on. The background shows a clean, professional lab environment with a white wall and a blue cabinet. A timestamp '2024.8.16' is visible in the bottom right corner of the photo.

21	GX-B1377/22-F-24252	2024. 8. 20	除击穿电压不合格外，其余所检项目合格，详见内页。	
22	GX-B1378/22-F-24198	2024. 8. 20	所检项目合格	

23	GX-B1378/22-F-24199~F-24203	2024. 8. 20	所检项目合格	
24	GX-B1377/22-F-24253	2024. 8. 20	所检项目合格	

25	GX-B1377/22-F-24254	2024. 8. 20	所检项目合格	
26	GX-B1377/22-F-24255	2024. 8. 20	所检项目合格	

27	GX-B1377/22-F-24256	2024. 8. 20	所检项目合格	
28	GX-B1501/21-F-24052	2024. 8. 20	煤尘具有爆炸性	
29	GX-B1501/21-F-24053	2024. 8. 20	煤尘具有爆炸性	
30	GX-B1502/21-F-24052	2024. 8. 20	II类, 自燃	
31	GX-B1502/21-F-24053	2024. 8. 20	II类, 自燃	

32	GX-B1502/21-F-24054	2024. 8. 23	II类, 自燃	
----	---------------------	-------------	---------	--