


序号	报告编号	发布日期	结论	影像资料
21	GX-B1341/24-8-24040	2024. 8. 30	综合判断：合格	
22	GX-B1341/24-8-24041	2024. 8. 30	综合判断：合格	

23	GX-B1341/24-8-24042	2024. 8. 30	综合判断：合格	 <p>2024-08-29</p>
24	GX-B1341/24-8-24043	2024. 8. 30	综合判断：合格	 <p>2024-08-29</p>
25	GX-B1343/21-8-23018	2024. 8. 30	副井-北风井通风系统1708.9Pa；辅助斜坡道-北风井通风系统1742.7Pa；主竖井-南风井通风系统1213.2Pa。	 <p>2024-08-29</p>

26	GX-B1347/21-8-23018	2024. 8. 30	综合指标89.4%，大于72%，合格。	 <p>2024-08-29</p>
----	---------------------	-------------	---------------------	---