

序号	报告编号	发布日期	结论	影像资料
1	GX-B1363/22-A-24527	2024/10/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
2	GX-B1364/22-A-241131	2024/10/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
3	GX-B1364/22-A-241132	2024/10/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
4	GX-B1364/22-A-241133	2024/10/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
5	GX-B1364/22-A-241134	2024/10/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
6	GX-B1369/20-A-24008	2024/10/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
7	GX-B1364/22-A-241142	2024/10/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
8	GX-B1364/22-A-241143	2024/10/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
9	GX-B1364/22-A-241130	2024/10/9	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
10	GX-B1364/22-A-241115	2024/10/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
11	GX-B1364/22-A-241116	2024/10/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
12	GX-B1364/22-A-241117	2024/10/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
13	GX-B1364/22-A-241118	2024/10/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
14	GX-B1364/22-A-241139	2024/10/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
15	GX-B1364/22-A-241140	2024/10/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
16	GX-B1364/22-A-241138	2024/10/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
17	GX-B1364/22-A-241136	2024/10/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
18	GX-B1364/22-A-241137	2024/10/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
19	GX-B1364/22-A-241135	2024/10/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
20	GX-B1363/22-A-24520	2024/10/9	全厚度拉断为1048N/mm，全厚度拉断伸长率为33%，其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
21	GX-B1509/20-A-24030	2024/10/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
22	GX-B1363/22-A-24518	2024/10/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
23	GX-B1363/22-A-24519	2024/10/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
24	GX-B1363/22-A-24521	2024/10/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
25	GX-B1363/22-A-24522	2024/10/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
26	GX-B1363/22-A-24517	2024/10/9	所检项目合格。	 A photograph showing two technicians in light-colored work uniforms inspecting a large, dark-colored industrial furnace or boiler. The furnace has a large, conical metal chimney stack on top. One technician is on the left, looking into the furnace's opening, while the other is on the right, wearing blue gloves and looking at the furnace's control panel. The background shows a window with a red frame and a white wall. A date stamp '2024.10.01' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
27	GX-B1364/22-A-241148	2024/10/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
28	GX-B1364/22-A-241149	2024/10/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
29	GX-B1364/22-A-241150	2024/10/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
30	GX-B1364/22-A-241152	2024/10/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
31	GX-B1364/22-A-241153	2024/10/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
32	GX-B1364/22-A-241154	2024/10/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
33	GX-B1364/22-A-241155	2024/10/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
34	GX-B1364/22-A-241156	2024/10/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
35	GX-B1364/22-A-241157	2024/10/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
36	GX-B1364/22-A-241158	2024/10/11	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
37	GX-B1364/22-A-241159	2024/10/11	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
38	GX-B1364/22-A-241160	2024/10/11	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
39	GX-B1364/22-A-241161	2024/10/11	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
40	GX-B1364/22-A-241162	2024/10/11	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
41	GX-B1364/22-A-241163	2024/10/11	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
42	GX-B1363/22-A-24528	2024/10/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
43	GX-B1363/22-A-24530	2024/10/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
44	GX-B1363/22-A-24531	2024/10/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
45	GX-B1363/22-A-24532	2024/10/10	所检项目合格。	 <p>2024/10/08</p>

序号	报告编号	发布日期	结论	影像资料
46	GX-B1364/22-A-241151	2024/10/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
47	GX-B1463/22-A-24001	2024/10/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
48	GX-B1463/22-A-24002	2024/10/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
49	GX-B1463/22-A-24003	2024/10/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
50	GX-B1363/22-A-24529	2024/10/12	所检项目合格。	